

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBM
(Other
verse side)DATE
Sub on re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032592 - (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NONE

7. UNIT AGREEMENT NAME

NONE

8. FARM OR LEASE NAME

C.C. Fristoe "a" NCT-2

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Justis-Tubb-Drinkard

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3, T-25-S, R-37-E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surfaceWell is located 330' from the East Line, and 330' from the
North Line of Section 3, T-25-S, R-37-E, Lea County, N. M.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3184' (D. F.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

The following work has been completed on subject well:

1. Pull pump equipment, and perforate 2 7/8" Casing with two
jet shots at 6017', 6022', 6035', 6057', and 6062'.
2. Acidize the perforations with 3000 gals 15% NE acid with ball
sealers between stages. Swab well. No new production.
3. WELL SHUT IN, Effective 7:00 A. M. August 12, 1966.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dan Gillett
Dan Gillett

TITLE Assistant District

DATE August 22, 1966

(This space for Federal or State office use)

Superintendent

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

*See Instructions on Reverse Side

AUG 23 1966

J. E. Gordon

J. E. GORDON

ACTING DISTRICT ENGINEER