Form 3160-5 UNITED STATES (June 1990)

a a si com E. O. 3032 1802

DEPARTMENT OF THE INTERIOR

MODRIS, NEW MEDICO 88246

FORM APPROVED Iget Bureau No. 1004-0135 Expires. March 31, 1993

5. Lease Designation and Serial No. LC 032592(a)

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

2

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

BUREAU OF LAND MANAGEMENT

I. Type of Well Oil Gas Well Well Gas		0.000
Vill Gas Well Other 2 Name of Operator		8 Well Name and No. No. 8 - C.C. Fristoe A Fed. NCT
<u>Chuza Operating</u>		9. API Well No.
3 Address and Telephone No	s 79710	30 025 20929
P.O. Box 51010, Midland, Texas	10. Field and Pool, or Exploratory Area	
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		Justis Blinebry
		11. County or Parish, State
990' FSL & 402' FEL of Section 3, T25S, R37E, Unit. Ltr. P		Lea County, NM
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Aftering Casing	Conversion to Injection
	X Ouher P&A	Dispose Water
		(Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Proposal for plugging and abandonment:

Wellbore Data: 8 5/8" set @ 1011', cemented to surface, CIBP @ 6075' w/35' cement on top in 2 7/8" production casing. CIBP @ 5290' in 2 7/8" production casing, perforations @ 4948-4977'.

Propose to pump 2 7/8" wellbore full of cement, remove wellhead and install dry hole marker. 🗶

Well to be P & A upon approval of sundry notice.

Check 8 1/4 - 178 co If coment no to be spolled	ging on	rules for	coment to	surface
to be spolled	from a	t least	1065 To	recipación P.W.C.
Signed Warf Culture	Tule Regu	latory Agent	APPROVIDE 6-1	5-98
(This space for Federal or State office use)			CHESTER	
Approved by	Trile	BUREA ROG	JUL 1 3 1998	