			M. OIL CONS. COMMISSION		
Form 3160-5 (June 1990)	UNITED ST DEPARTMENT OF T BUREAU OF LAND N	HE INTERIOR H	SOX 1380 ORM APPROVED NEAR AND 101013 5. Lease Designation and Serial No.		
<b>Sur</b> Do not use this form fo Use ".	71-032511F 6. If Indian, Allottee or Tribe Name				
	SUBMIT IN TR	IPLICATE	7. If Unit or CA, Agreement Designation		
1. Type of Well         Yoil       Gas         Well       Well         2. Name of Operator         ARCO Permian         3. Address and Telephone No.	8. Well Name and No.           SOUTH JUSTIS UNIT"A" #12           9. API Well No.           30-025-20995           10. Field and Pool, or exploratory Area				
P.O.BOX 1610, M 4. Location of Well (Footage, Se 1650 FNL & 99	JUSTIS BLBRY-TUBB-DKRD 11. County or Parish, State				
<u>11-25S-37E</u>			LEA NM		
12. CHECK APP	ROPRIATE BOX(s) TO I	NDICATE NATURE OF NOTICE, REPO	DRT, OR OTHER DATA		
TYPE OF SUBM	ISSION	TYPE OF AC			
X Notice of Int		Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other <u>ADD PERFS &amp; TR</u>	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of maltiple completion on Well Completion of Report and Log form.)		
give subsurface locatic PROPOSE TO: 1. POH W/PROD 2. CO TO 5560	CA. PBD. EXISTING PERFS 5214	is for all markers and zones pertinent to this work.)*	of starting any proposed work. If well is directionally drilled		
14. I hereby certify that the form	ogoing is true and correct ) Gognell	Title AGENT			
(This space for Federato) St Approved by	MAR, EXAL	WTitle PETROLEUM ENGINEER	Date JUN 2 9 1995		
Conditions of approval, it a	ny:	,			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## **WORKOVER PROCEDURE**

DATE: May 19, 1995										
WELL & JOB: SJU A-12			DRILLED: 1964							
LAST WORKOVER: 12/88 Pull Packer			FIELD: Justis	COUN						
BY: W.C. Heard	<b>TD:</b> 6180'		<b>PBD:</b> 5660'	DATU						
CASING: SURFACE: PROD:	<u>SIZE</u> 9-5/8" 7"	<u>WEIGHT</u> 32# 23/20#	<u>GRADE</u> H40 J55/N80	<u>SET @</u> 1036' 6180' DVT @ 4903'	<u>SX_CMT</u> 546 200 432 HYS400	TOC surf-circ 4950'-calc 465'-TS				
PERFORATIONS: Open Perfs: Blinebry 5214-5645': plugged: Tubb/Drinkard 5944-6117'										
TUBING: SIZE: 2-3/8" WEIGHT: GRADE: MISC: TAC @ 4975'		THREAD: EUE/Buttress		JOINTS:	BTM'D @					

HISTORY AND BACKGROUND: During workover of 1988, pulled CA and LD lok-set packer. Reran tubing, pump and rods. No record of work performed since December, 1988. (Note: check Production files to verify CA)

SCOPE OF WORK: Pull CA, clean out and stimulate existing perfs.

## PROCEDURE

1. MIRU, pull CA. Visually inspect tubing and determine if work string is needed.

2. TIH with bit and casing scraper and CO/DO to 5660'. POH.

3. Acidize as per attached Engineering recommendation.

4. Run CA as per Production Department design and TOPS.

W. C. Heard

J. E. Shields

## WELLBORE SCHEMATIC

