

SUNDRY NOTICES AND REPORTS ON WELLS

Use this form for notices and reports on wells, including but not limited to: (1) notices of intention to drill, (2) reports of completion, (3) reports of shut-in, (4) reports of abandonment, (5) reports of repairs, (6) reports of operations, (7) reports of surveys, (8) reports of tests, (9) reports of measurements, (10) reports of observations, (11) reports of accidents, (12) reports of fires, (13) reports of explosions, (14) reports of other incidents.

AS WELL AS OTHER

Line Real Oil Company

Box 460, Hobbs, New Mexico

1. LOCATION OF WELL Report location clearly and in accordance with any State requirements.*

At surface

660' FNL & 1980' FWL Sec. 1, T-25S, R-36E, Lea County, New Mexico, NMPM.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3252 GR

12. COUNTY OR PARISH

Lea

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRAC TREAT

MULTIPLE COMPLETE

FRAC TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion or Completion or Re-completion Report and Log form)

2. OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated cost of operations. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all marked points in this work.)*

It is proposed to plug and abandon Wells B-1 No. 2 and failure to retrieve fish consisting of 25 jts of 4 1/2" DP, 1 sub, and 39 drill collars.

Proposed procedure as follows:

1. Plug with 500 sx cmt. W/8% gel through DP @ 2565'
2. WOC
3. Pump 500 sx cmt through 4 1/2" DP W/8% gel & 1/4" tuf plug.
4. Pump 150 sx Class "A" cmt through 4 1/2" DP 1220 to
5. Fill with mud and set 10 foot cement and plug at surface.
6. Return to original condition.
7. Set 4' marker on well site.

ILLEGIBLE

SIGNED: ROBERT GAULT III

TITLE Staff Supervisor

DATE 1-2-65

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

US NMOC-2, PAN AM HOBBS -3, AT ROS-2, CALIF HOUS & MID

*See Instructions on Reverse Side

