Form 3160-5 (December 1989)

P.O. BOX 1980
HOSSS, NEW MEXICO Budget Bureau No. 1004-0

Budget Bureau No. 1004-0135

Evaires Sentember 10, 1990

DUDEAU OF LAND MAN	A /~E.BAL-A!		
BUREAU OF LAND MANA	1	5. LEASE DESIGNATION AND SERIAL NO.	
		NM-05254	
SUNDRY NOTICES AND REPO			
not use this form for proposals to drill or to deepe Use "APPLICATION FOR PERMIT"	an or reently to a different reservoir.	3. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUBMIT IN TRIPLICATE 1. TYPE OF WELL GAS WELL OTHER		7. IF UNIT OR CA, AGREEMENT DESIGNATION	
		8. WELL NAME AND NO.	
NAME OF OPERATOR		South Justis Unit "C" #23	
ARCO Oil & Gas Company		9. API WELL NO. 30-025-21057	
	(915) 688-5672	10. FIELD AND POOL, OR EXPLORATORY A	
P.O. Box 1610, Midland, TX 79702 LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description of the control of the con	` '	Justis Blbry-Tubb-Dkrd	
. LOOK TON OF WELL (1 collage, cec., 1., 1., m., or curvey occurre		11. COUNTY OR PARISH, STATE	
330 FNL & 1650 FEL (Unit Letter B)			
26-25S-37E		Lea County, NM	
CHECK APPROPRIATE BOX(S) TO IN	DICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF AC	TION	
NOTICE OF INTENT		CHANGE OF PLANS	
		NEW CONSTRUCTION	
X SUBSEQUENT REPORT		NON-ROUTINE FRACTURING	
	CASING REPAIR	WATER SHUT-OFF	
		CONVERSION TO INJECTION	
FINAL ABANDONMENT NOTICE	☐ ALTERING CASING ☐	conversion to injection for South Justic Unit	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s	☐ ALTERING CASING ☐ ☑ Other Work Over wellbore (NOTE: Report rest Completion tate all pertinent details, and give pertinent dates	for South Justis Unit alts of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any	
	ALTERING CASING Actions and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs f/	for South Justis Unit Ilts of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Action Work over wellbore (NOTE: Report resure Completion) tate all pertinent details, and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs f/s & pump to 5927. RDPU 9-30-93.	for South Justis Unit alts of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Action Work over wellbore (NOTE: Report resure Completion) tate all pertinent details, and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs f/s & pump to 5927. RDPU 9-30-93.	for South Justis Unit Ilts of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Actions and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs f/	for South Justis Unit of Multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Action Work over wellbore (NOTE: Report resure Completion) tate all pertinent details, and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs f/s & pump to 5927. RDPU 9-30-93.	for South Justis Unit of multiple completion on Well or Recompletion Report and Log form.) including estimated date of starting any all markers and zones pertinent to this wo	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Accepted FOR	for South Justis Unit Ilts of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Accepted FOR	for South Justis Unit of multiple completion on Well or Recompletion Report and Log form.) including estimated date of starting any all markers and zones pertinent to this wo	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Action Work over wellbore (NOTE: Report resure Completion) tate all pertinent details, and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs f/s & pump to 5927. RDPU 9-30-93.	for South Justis Unit Ills of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo 5106-5949. Acidize perfs 5092-5962	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Accepted FOR	for South Justis Unit Ilts of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo 5106-5949. Acidize perfs 5092-5962	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982	ALTERING CASING Accepted FOR	for South Justis Unit Ills of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo 5106-5949. Acidize perfs 5092-5962	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sproposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982 w/10,000 gals. RIH w/CA: 2-3/8 tbg, rod:	ALTERING CASING And other Work over wellbore (NOTE: Report resultate all pertinent details, and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs first way 19 1993. ACCEPTED FOR PROVIDE SET OF THE PR	for South Justis Unit Ills of multiple completion on Well or Recompletion Report and Log form.) , including estimated date of starting any all markers and zones pertinent to this wo 5106-5949. Acidize perfs 5092-5962	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sproposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982 w/10,000 gals. RIH w/CA: 2-3/8 tbg, rod:	ALTERING CASING And other Work over wellbore (NOTE: Report resultate all pertinent details, and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs first way 19 1993. ACCEPTED FOR PROVIDE SET OF THE PR	for South Justis Unit Ilts of multiple completion on Well or Recompletion Report and Log form.) Including estimated date of starting any all markers and zones pertinent to this wo 5106-5949. Acidize perfs 5092-5962	
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sproposed work. If well is directionally drilled, give subsurface loc 9-21-93. POH w/CA. CO fill, junk & CIBP to 5982 w/10,000 gals. RIH w/CA: 2-3/8 tbg, rod: 4. I hereby certify that the foregoing is true and correct SIGNED Show Library Library.	ALTERING CASING And other Work over wellbore (NOTE: Report resultate all pertinent details, and give pertinent dates ations and measured and true vertical depths for PBD. Press test csg to 500#. Add perfs first way 19 1993. ACCEPTED FOR PROVIDE SET OF THE PR	for South Justis Unit of multiple completion on Well or Recompletion Report and Log form.) including estimated date of starting any all markers and zones pertinent to this wo 5106-5949. Acidize perfs 5092-5962	