Form	9-331
(May	1963

TEST WATER SHUT-OFF

(Other)

STIDMENT IN TRIPILI

Form approved. Budget Bureau No. 42-R1424.

U l/s	DSIAIES	Other instructions
EPARTMEN.	OF THE INTERIOR	verse side)

ALTERING CASING

DEPARTMEN. OF THE INTERIOR verse side) GEOLOGICAL SURVEY		5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY N	eservoir.	
OIL CAS WELL OT:	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR	OIL COMPANY, ISC. - Nobbe, New Mexico 88240	9. WEDS 110 " 1"
4. LOCATION OF WELL (Report loc. See also space 17 below.) At surface	ation clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT SURVEY OR AREA SURVEY OR AREA
2310 FML 6 990	Unit R Sec. 11 T-25-8: R-37- 12. COUNTY OR PARISH 13. STATE	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OF PARISH 15. STATE
16. Che	ck Appropriate Box To Indicate Nature of Notice,	
NOTICE OF	F INTENTION TO: PULL OR ALTER CASING WATER SHUT	SUBSEQUENT REPORT OF:

ABANDON* SHOOT OR ACIDIZE (Other) -CHANGE PLANS (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

- Hove in, rig up, install BOP and pull dual strings tubing.
- Perforate 5059, 63, 70, 83, 5102, 06, 15, 19, 23, 29, 37, 47, 54, 58, 63, & 79'.
- Run ret. BP to 5735'; packer at 4975'.

MULTIPLE COMPLETE

- Frac in 4 stages w/80,000 gal. galled frac fluid plus 120,0000 20/40 sand.
- Pull tubing, packer and retrievable BP.
- Run dual strings tubing and susb Blinebry some to test. Bun rods Tubb-Drinkerd and place back on production.

I hereby ce Sheldon Ward	TITLE ATO	a Superintendent	DATE
(This space for Federal or State office use)	APPROVER		VED.
APPROVED BY	TITLE	DATE	
	FEB () + 1 97 ()		1970

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State officea. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963---O-685229

867-851