	UNITED STATES RTMENT OF THE INTERIOR AU OF LAND MANAGEMENT	M.M. Oll Co. J. Jivi 1625 N. French Dr. Hobbs, NM 88240	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 3 1 ,1993		
SUNDRY NO Do not use this form for proposa Use "APPLICAT	5. Lease Designation and Serial No. NM 0321613 6. If Indian, Allottee or Tribe Name				
1. Type of Weil	7. If Unit or CA, Agreement Designation				
2. Name of Operator CONOCO Inc 3. Address and Telephone No.	8. Well Name and No. Jack B-26 #2 9. API Well No.				
10 DESTA DR. STE. 100W, MIDLAND, TX 79705-4500 (915) 686-5580 4. Location of Well (Footage. Sec., T. R. M. or Survey Description)			30-025-21065 10. Field and Pool, or Exploratory Area Justis Tubb-Drinkard		
1980' FNL & 660' FWL, Sec. 26, T24S, R37E, E			11. County or Parish, State Lea, NM		
TYPE OF SUBMISSION		(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION			
Notice of Intent	Abandonm Recomplet Plugging E	ion Back	Change of Plans New Construction Non-Routine Fracturing		
Final Abandonment Notice	Casing Re	•	Water Shut-Off Conversion to Injection Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned 3/19/00, per the attached procedure and reference data from Pool Co.

14. I hereby certify that the foregoing in true and correct	R	Reesa R. Wilkes		
signed Killsa Willes	Title S	r. Staff Regulatory Assistant	Date _	03/29/00
(This space for Federal or State office use) (OPIG. SGD.) DAVID F. GL Approved by Conditions of approval if any:	ASS	PETROLEUM ENGINEER		MAR 3 0 2000
BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, F			l unit	
Title 18 U.S.C. Section 1001, makes it a crime for any person kno or representations as to any matter within its jurisdiction.	owingly and willful	ly to make to any department or agency of the United Stat	tes any false,	fictitious or fraudulent statemer
JC GWW	*See Inst	ruction on Reverse Side		B

Form 3160-5 'UNI	ITED STATES	FORM APPROVED Budget Bureau No. 1004-0135	
(June 1990) DEPARTMEN			
. BUREAU OF	LAND MANAGEMENT	Expires: March 31, 1993 5. Lease Designation and Serial No.	
SUNDRY NOTICES	AND REPORTS ON WELLS	N.M. 0321613 6 If Indian, Allottee or Tribe Name	
Do not use this form for proposals to d	rill of to deepen or reentry to a different reservoir. IN POTMIT—" for such proposals		
SUBMI	TIN TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of Well "OII Gas Well Well Other	• • •	8. Well Name and No.	
XX Well Other 2. Name of Operator		Jack B 26 2	
CONOCO INC.		9. API Well No.	
3. Address and Telephone No.		30-025-21065	
<u>10 Desta Dr. St. 100W Midland</u> 4. Location of Well (Footage, Sec., T., R., M., or Survey E	10. Field and Pool, or Exploratory Area		
- Column of wenth outage, Sec., 1., K., M., of Survey L		Justis Tubb-Drinkard	
Sec 26 T 24S R 37E U.L.E	. 1980'FNL & 660" FWL		
·		Lea, Jal New Mexico	
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	IT, OR OTHER DATA	
TYPE CF SUBMISSION	TYPE OF ACTION	•	
Notice of Intent		Change of Plans	
<u> </u>	. Recompletion		
Subsequent Report	Casing Repair	Non-Routine Fracturing	
Final Abandonment Notice	Altering Casing	Conversion to Injection	
	xxouter totaly plugged out	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (orm.)	
13. Describe Proposed or Completed Operations (Clearly state a	all pertinent details, and give pertinent dates, including estimated date of starting cal depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled,	
GIH w/work string to 3800' 1	oad hole w/brine try to test 4 1/2 cas	ing would not hold	
pressure had casing leaks 35	00-3783' spotted plug 35 sks 3800'bott	om : tag plug 3450±	
spotted 20 sks plug on top o	f 3450': shut down tag plug 3275' tes	ted 4 1/2 casing	
held 5001bs psi. poh w/tub G	IH w/3 5/8" casing cutter: cut off 4	1/2" casing at 2500'	
Run 4 1/2" spear and pull 80	,000 lbs on casing, casing would not c	ome free 2500' of	
	pprox.25000 lbs. try to pump into casi		
	al from BLM to spot a 25 sks plug from		
	shot hole 2-shot per/ft. at 1120' got	· •	
accine INT several under T	אלא איז איז איז איז איז איז איז איז איז אי		
	5/8" to cover salt section, dug up sur	•	
valve, had a strong blow app	. 150 psi. coming from zone down below	surface pipe t.d.	
309':pump 160 sks down 13 3/	8" : displace cmt to 259' inside 13 3/8	8 squeeze off 13 3/8"	
14. I hereby certify that the foregoing is true and correct			
Signed hereby that the rotegoing is that and correct	Tide CONT_ Sup	Date <u>3- 19-00</u>	
(This space for Federal or Stat SGD.) DAVID F	GLASS	MAR 3 0 2000	
Approved by Conditions of approval, if any:	Tide PEINOLEUM ENGINEEM	Date O V ZINU	
)	Abproved as to plugging of the well Each dra under bond is retained and		

.

÷

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

۵. ۲.

ал — **К** С



1100 lbs psi, shut down, next day check 13 3/8" for blow: 13 3/8" casing had no blow had no pressure: went in hole w/wireline shot 2-hole inside 4 1/2" casing at 240' shot through 4 1/2 casing and 9 5/8" casing. INT. got eirculation up, 13 3/8, 9 5/8, and 4 1/2" casings. Mix cement 200 sks fill up 13 3/8, 9 5/8, and 4 1/2" casings, from 240' to surface w/cmt. shut down cut off well head install dry hole marker clean up location and move off.

(# 22,749.52 ast) R.L Dic Ale CONSIC INC. Bry any JACK 0-26-2 6.71 2210 Posp ring S 60 BBL GEL BRINE LOAd 41/2 CASING 3.41" 23/8 Disp Pluig 17000 1316 55 545 81.32.2.1781= 12.13 332 Sturry Disp Ruix 55345263 % 42: Nos pilling 3 8.25 BOL TO mix 0 352 255(5× 1.32×.178)= 5.88 BBC 54/17 Plug 2 25515 16.3%42 = 3.75 BOLTO MIX 40515 X 1.32 X. 1781 9.40 BBC Slarry Plug 3 40512637.42= 6.0 BBLTOMIX 160503 × 1.32×. 1181= 37.61 BBC Shurry Flui 4 1605(5×63×42 = 24 BOLTO MIX 412 200513.11.32,2.1781= 47,02 B31 Swirt 9518 Pug 5 2005132631422 30,0 1336 TOmix 13/8 Fill 412 + 998 + 1378 CASING WICONT From 240 But To Surface 200515 3-17-00) Perturted 41/2 + 95/8 Utsing 240 (3-17-00) Runp 160515 for 1338 Surface Displace cont To 259 Squeeze off GAS Flow Blue TAY TOP of CINT 1010 1.3 2 Shots 1120 BUE GEU (3-15-00) Top of Uni 2250 "Fut HIL2" CASING OFP TRY TO Pull Casing Could Pull CHING 80,000 25545 (2) 4112 CASING Cutters 2500 (3-15.00) Spotteo 20545 Plugs Could Not pump wto 45ing 3545 2550 Botton of int 同志に THY TOP OF CONT 3275 (\mathcal{V}) (3-13 00) 55 うれう (3-13-0C) Hoten of CAT 3000

•

٠

41.51

