

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

Orig³cc: OCC, Hobbs
cc: Southern Region (West Texas)
cc: file

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Wimberly WN
9. Well No. 9
10. Field and Pool, or Wildcat Justis Blinebry
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator SINCLAIR OIL CORPORATION
3. Address of Operator P. O. Box 1920, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>25S</u> RANGE <u>37E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3082' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well presently completed in Blinebry perms. 5334-5527'. TD 5600', PBTD 5548'.

PROPOSE TO: Set retrievable bridge plug in 4-1/2"OD casing @ approx. 5300'. Jet perforate @ approx. following depths 5095, 5114, 5122, 5126, 5140, 5151, 5157, 5180, 5188, 5207, 5210, 5236 & 5238'. Breakdown perms. w/approx. 2,000 gals. BDA. Sand water frac w/approx. 30,000 gals. mod. brine plus 30,000' sand. Swab test and return to production higher in same formation (Blinebry).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Brown TITLE Superintendent DATE 3-6-69

APPROVED BY James J. Stoney TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: