

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-21152</u>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>Jamison</u>
8. Well No. <u>5</u>
9. Pool name or Wildcat <u>Langhe Mrtt. & 7 RVS/Queen</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>INTJ.</u>
2. Name of Operator <u>Smith & Marrs Inc.</u>
3. Address of Operator <u>P.O. Box 863 Kermit, TX. 79745</u>
4. Well Location Unit Letter <u>H</u> : <u>1315</u> Feet From The <u>EAST</u> Line and <u>1325</u> Feet From The <u>North</u> Line Section <u>21</u> Township <u>24S</u> Range <u>37E</u> NMPM <u>LEA</u> County <u>LEA</u>

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3229 SR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>


SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1 20 SKS @ 3300' - 3200' & tag
 - 2 20 SKS @ 2200' - 2100'
 - 3 Perf & squeeze 45 SKS @ 875 - 775' & tag
 - 4 15 SKS @ 60' to surface → 10 3/4 SHOE 286-186 TAG
- 8 5/8 - 825-425 SKS
4 1/2 - 3354-100 SKS
open hole 3354-3630

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.



Install Dry Hole Marker - Cir. 9.5" #1

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Pres. DATE 11-15-01

TYPE OR PRINT NAME _____ TELEPHONE NO. 913 586-3076

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____