

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
Name of Operator Chevron U.S.A. INC.	8. Farm or Lease Name Continental State
Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. 1
Location of Well UNIT LETTER <u>B</u> , 1980 FEET FROM THE <u>East</u> LINE AND <u>860</u> FEET FROM THE <u>North</u> LINE, SECTION <u>5</u> TOWNSHIP <u>24S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat State Line Ellenburger
11. Elevation (Show whether DF, RT, CR, etc.) 3286	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Locate and repair csg leak

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PU pkr and RBP, set RBP at 11,946, pkr at 11,916. Test for casing leaks and isolate from 5586 to 5617. Pump thru leak w/inj rate 1100psi, TIH to 5648, pmp 2sx 12/20 sd dn tbg. TIH w/cmt ret to 5463, pmp thru retainer, ok. Set at 5463, load casing 500psi, est inj rate, pmp 5bbl FW and 175 sx C, displace w/15bbl FW. Shut down on vac. Sting out of ret., rev 1/2 bbl cmt to pit. Tag cmt 5462, drlg to 5885, circ wellbore. Test to 600psi, ok. FL overnite 0. RIH, tag fill at 11,906. Wash 30' of cement and scale 10' of sand. Circulate clean. Test PE in well, run rod string, space out, Turn over to production. Tst casing, ran PAL, Csg LMS log, load casing, holes at 5768, 5582, 5457. Set ret at 5280', ppd 100sx C1 H cmt, spot cmt slurry to ret, stg cmt in form, stg cmt 3 hrs. cap w/ 3sx, rev out, WOC. Drlg cmt from 5278 to 5795, circ. Swb, no fluid entry. CO to 12,131, circulate, Correct PBD 12,158, Ran production equip. Turn over to production. Work performed 7-23-87 through 8-30-87.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Abin TITLE Staff Drilling Engineer DATE September 11, 1987

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

TITLE DATE SEP 15 1987

ADDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670, Hobbs, NM 88240

Location of Well

UNIT LETTER B 1980 FEET FROM THE East LINE AND 860 FEET FROM  
North LINE, SECTION 5 TOWNSHIP 24S RANGE 38E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name  
Continental State

9. Well No.  
1

10. Field and Pool, or Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)  
3286

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

REMEDIAL WORK ☐  
REPAIR ABANDON ☐  
RE ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

locate and repair csg leak. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to locate leak and set cmt rtthr  $\pm$  50' above leak, squeeze leak, drill out retainer and cmt, circulate clean, test squeeze, return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Elmer J. McEskin

TITLE Staff Drilling Engineer

DATE July 17, 1987

Orig. Signed by  
Paul Kautz  
Geologist

TITLE

DATE

COPIES OF APPROVAL, IF ANY: