

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
Lease Designation and Serial No.
NM-14218

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco Exploration & Production, Inc.

3. Address and Telephone No.

P. O. Box 3109, Midland, TX 79702 (915) 688-4438

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter P, 660' FSL, 989' FEL
Section 26, Township 24-S, Range 37-E

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. Fristoe

C.C.B. FED NCT 2 #10

9. API Well No.

30-025-21413

10. Field and Pool, or Exploratory Area

Justis Paddock North

11. County or Parish, State

Lea, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. RU on northside, set 2 7/8" CIBP @ 4850' (Paddock) Fill
2 7/8" csg w/60 sx cmt 4850' - 2500'
2. RU on southside, set 2 7/8" CIBP @ 4850' (Paddock) Fill
2 7/8" csg w/60 sx cmt 4850' - 2500'
3. Cut 2 7/8" csqs @ 2500', L/D both strings. Spot 100 sx plug
2500' - 2200' (8 5/8 shoe) Tag @ 1943'
4. Displace hole w/salt gel mud 9.5# brine w/25# gel P/BBL
5. Spot 100 sx plug 1200' - 900' (T-Salt) no tag. Re-spot
100 sx plug 1220' - 900' WOC Tag @ 790'
6. Spot 18 sx plug 60-Surf, install dry hole marker 7/19/00

Approved as to plugging of the well
under bond & retained until
the well is plugged.

14. I hereby certify that the foregoing is true and correct

Signed

(This space for Federal or State office use)

Approved by
Conditions of approval, if any

Title

Title

Date

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

GWW