Form 9-331 (May 1963)

Regular

## UN ED STATES SUBMIT IN TRIP (Other instruction verse side) GEOLOGICAL SURVEY

TE\*

Form approved. Budget Bureau No. 42-R1424.

5.	1.	EASE	DESIG	NATIO	) N _ A	ND	SER	IAL	NO
]	$\sim$	-03	3259	2 <b>-</b> #	bii				

	6. IF INDIAN, ALLOTTEE OR
undry notices and reports on wells	

(Do not use this for	RY NOTICES AND REPORTS ON WELLS  m for proposals to drill or to deepen or plug back to a different reservoir. se "APPLICATION FOR PERMIT—" for such proposals.)	G. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	——————————————————————————————————————	7. UNIT AGREEMENT NAME
METT X METT CAR	OTHER	24.25
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
	TRUM Inc.	C.O. Printee "b" NOT-2
3. ADDRESS OF OPERATOR		9. WELL NO.
	P. O. Tox 728 - Mehbos, New Mexico	10
	ort location clearly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT
See also spa <b>c</b> e 17 below.) At surface		*Ses below
Well located 98	+ 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
Line of Section		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Sec. 26, T-24-S, R-37-E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
Pegular	3181' (7. 7.)	Lea N. M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16.

Check Appropriate Box to indicate Hardie of Honce, Report, of Other Board						
NOT	ICE OF INTENTION TO:	SUBSEQUENT REPORT OF:				
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	x	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING		ABANDONMENT*	
REPAIR WELL	CHANGE PLANS		(Other)			
(Other)		<u></u> _	(Note: Report res Completion or Reco	ults of multiple ompletion Report	completion on Well and Log form.)	· 

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Total Depth - 6115: 8 5/8" O. D. Casing Cemented at 1074:

Justis Plinetry Zone: Ran 6031' of 2 7/8" 0. F. Casing, 6.50 LP, J-55, NEW, and cemented at 6031', Plug at 5027'.

Justis Tubb Drinkard Rone: Ran 6100' of 2 7/8" 0. D. Gasing, 6.50 LB, J-55, MDM, and cemented at 6110', Plug at 6080'.

Spot 500 mals acetic acid down each string of 2 7/8" 0. D. Casing. Cemented above strings of 2 7/8" 0. D. Casing with 450 Sx. Trinity Lite Wate with 5/10% FPA in first 300 Sx. Job complete 12:30 A. M. September 5, 1965. Tested above strings of 2 7/8" O. D. Casing for 30 minutes with 1500 P. S. I. from 11:00 A. M. to 11:30 A. M. September 9, 1965. Tested O. K. Job complete 11:30 A. M. September 9, 1965.

18. I hereby certify that the forceolog is	true Field Foreman	DATE September 10, 1965
(This space for Federal or State offi-	ce use)	
APPROVED BY		DATE