Form 9-331 (May 1963)

ES SUBMIT IN TRIPLICA (Other instructions on verse side)

| | Form a Budget | Bure | ea. Lu N | o. 42-R14 | 24 |
|-------|---------------|------|-------------|-----------|----|
| LEASE | DESIGN | TION | AND | SERIAL N | o. |

| . DLI | NM-12610 | | |
|--|--|---|---|
| SUNDRY (Do not use this form for Use ") | NOTICES AND REPORTS OF proposals to drill or to deepen or plug back APPLICATION FOR PERMIT—" for such proposals." | N WELLS | 6. IF INDIAN, ALEOTTER OR TRIBE NAME |
| OIL GAS | other | NEGIVER | 7. UNIT AGREENENT NAME |
| TEXACO Inc. | U | AUGIO | C.C. Fristoe 'B' Federal |
| P.O. Box 728 - Ho | DDU 1 11CH 11CH 1CC 1CC | DESS, NEW TO | 9. WELL NO. |
| See also space 17 below.) At surface Well loca | ocation clearly and in accordance with any Silted 1980' from the North 1 ection 35, T-24-S, R-37-E, | ine and 1980 From Unit Letter F. | Justis Blinebry 11. SEC., T., R., M., OR BEK. AND SURVEY OF AREA Sec. 35, T-24-S, R-37-E |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, R | er, GR, etc.) | 12. COUNTY OR PARISH 13. STATE |
| Regular | 3183' DF | | Leas New Mexico |
| TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPL proposed work. If well in nent to this work.)* The following work 1. Perforated down 5121', 5128', 5 198', 5208', 5 2. Fraced w/25,000 Adomite in 5 ec blocks between 3. Swab, test and 4. On 24 hour PT 6 | PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS ETED OPERATIONS (Clearly state all pertinent directionally drilled, give subsurface location on subject well has been consubject well has been consubject, 5137', 5144', 5149', 5214', 5216', 5220', 5222', 5214', 5216', 5220', 5222', 5214', 5216', 5216', 5220', 5222', 5216', 5216', 5220', 5222', 5216', 52 | water shut-off FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomple details, and give pertinent dates, ns and measured and true vertica completed: 1 JSPI @ 5099', 5102 5161', 5172', 5176' 5226', 5242', 5246' w/l ppg 20-40 sand a ad of each stage usi with lease crude. 7, 1971, flowed 54 b | of multiple completion on Well etion Report and Log form.) including estimated date of starting and depths for all markers and zones pertility. 5107, 5112, 5117, 5179, 5182, 5184, 5254 and 5256 and 25#/1000 gals Mark II ng 75-250# Unibead |
| 18. I hereby certify that the for SIGNED (This space for Federal or APPROVED BY CONDITIONS OF APPROVED.) | State office use) TITLE | Sistant District perintendent ACCEPTED | PATE August 18, 1971 |
| | | AUG 1 | 9 1971 |

*See Instructions on Reverse Side, S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO

