(June 1990) DEPARTM BUREAU O SUNDRY NOTICE Do not use this form for proposals t	NIآ النالي STATES ENT OF THE INTERIOR F LAND MANAGEMENT ES AND REPORTS ON WELLS o drill or to deepen or reentry to a different reservoir. FOR PERMIT for such proposals	CONS. COMMISSION 1980 Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. LC 032650B 6. If Indian, Alottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well: OIL GAS WELL WELL WELL		8. Well Name and Number COATES, A. BC-
2. Name of Operator TEXACO EXPLOR	ATION & PRODUCTION INC.	27
3. Address and Telephone No. P.O. BOX 730, HC	DBBS, NM 88240 397-0426	9. API Well No.
4. Location of Well (Footage, Sec., T., R., M., or Surve Unit Letter K : 1650 Feet From T	y Description) The SOUTH Line and 1650 Feet From The	30 025 21428 10. Field and Pool, Exploratory Area JUSTIS BLINEBRY
WEST Line Section 24	Township 25S Range 37E	11. County or Parish, State LEA , NEW MEXICO
12. Check Appropriate	Box(s) To Indicate Nature of Notice, Re	
TYPE OF SUBMISSION		
 Abandonment Abandonment Abandonment Abandonment Abandonment Bugging Back Non-Routine Fracturing Casing Repair Attering Casing T.A. Contension to Injection OTHER: Tecomplete to Glorieta Dispose Water Other Report and the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*. Texaco Exploration and Production Inc. respectfully submits it's plans concerning notice AJM-006-96. The recompletion described below has been previously approved by the BLM (5/17/95). Due to workover priority, the work has not yet been performed. Despote the filed (i.e. application for non-standard proration unit). Objective: Texaco intends to plug back the subject well out of the Blinebry zone and recomplete uphole to the Glorieta. Tirl with bit and clean out to PBTD. Set CIBP within 100° of the uppermost Blinebry perforation and cap with 35° cement. Perforate Glorieta zone (exact interval to be determined). Acid stimulate Glorieta perforations. 		
	$\frac{3}{111 \text{ Engineering Assistant}}$	DATE 11/7/95
TYPE OR PRINT NAME Darrell (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	J. Carriger 	DATE 12/15/96