

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instruction re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM051998

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Lease

8. FARM OR LEASE NAME

BUNKIE Carlson B 13

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Justis Minebry

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 13-254-97E NMPM

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill on, to deepen or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CRA, Inc.

3. ADDRESS OF OPERATOR

Box 88, Jal., New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' from E line & 2310' from N line Sec. 13

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GL. 3086'

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☒
☒
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Feb. 9, 1966 - Producing Minebry 5255'-5268'-5279'-5299'-5323'-5346'-5374'-
5382'-5401'-5419'-5427'-5455'-5480'- one shot per/int. 36 BOPB.

2-14

We propose to perforate additional Minebry 5215'-5229'-5285'-
one per/int. Acidize with 3000 gal. HCl acid staging w/20 7/8"
balls. Frac w/35,000 gal. lease oil & 35,000 lb. sand & test.
Kill well and run tubing. Put well on.

18. I hereby certify that the foregoing is true and correct

SIGNED

L. E. Schaffer

TITLE

Production Superintendent

DATE

Feb. 9, 1966


(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled; and the depth to top of any left in the hole; method of closing top of well; and date well safe conditioned for final inspection looking to approval of the abandonment.

(U.S. GOVERNMENT PRINTING OFFICE: 1963 O-569229)

5010-1081