

31DU #6Y P/H

6-22-73

P&A

1. Rig up Xpert P/u

A CK Tbg Flowing press - 900#

B CK Csnq press - 4200#

C Installed Chocke on csnq bled to pit 3hr - Press 700

2 Connect Hucc on Tbg - Pm dn Tbg ^{w/ fresh wtr} 1000# drop To 100# After 50 bbls slow rise in Tbg press fr 50 bbls To 250 bbls (100# To 2000#) Pm 50 bbls @ 2000# 2 bbls per min - Csnq press increased fr 700# To 2000# while pm dn Tbg -

Tbg 15IP - 1400 - Csnq 15IP - 2000

Tbg on vac in 45min Csnq P-1200

S.I 3hr Tbg - P-200 Csnq P-1400

Hucc Pm 200 bbls fresh wtr dn Tbg @ 1BPM 500# press - Bled Csnq press To -0

Started wtr dn Csnq on vac 4hr T.P. - 0

Csnq Taking 25-30 bbls per - Start wtr dn Tbg & Csnq on vac 30-40 bbls per hr - (10hr)

6-23-73

S.I Tbg & Csnq @ 9:00 AM - Csnq show slight Blow on needle valve after 3hr - Tbg still had slight vac after 12hr S.I.

12 hr S.I. Csnq still not showing Press engage

Tank rental - 700.

Xpert P/u - 700

Hucc - 2000

Gang - 300

Drig Pipe -

Welder - 30