Form 3160-5 (June 1990)

## ED STATES DEPARTM.... OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

100 bs. NM 88240 Budget Bureau No. 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		Expires: March 31, 1993
		5. Lease Designation and Serial No.
		LC-057509
Use "APPLICATION FOR PERMIT" for such proposals		6. If Indian, Alottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well: GAS OTHER		8. Well Name and Number ERWIN, G. LB- FEDERAL NCT-1
2. Name of Operator		Elivini, O. ED- I EDETOE HOT-I
TEXACO EXPLORATION & PRODUCTION INC.  3. Address and Telephone No.		5
15 SMITH ROAD, MIDLAND, 1X 79705 915-687-737		9. API Well No. 30 025 21910
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, Exploaratory Area
Unit Letter B : 660 Feet From The NORTH Line and 2310 Feet From The		LANGLIE MATTIX 7 RVR QN GRAYBURG
EAST Line Section 26 Tow	rnship 24S Range 37E	11. County or Parish, State  LEA , NEW MEXICO
12. Check Appropriate Bo	ex(s) To Indicate Nature of Notice Re	eport, or Other Data
Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data  TYPE OF SUBMISSION  TYPE OF ACTION		
	Abandonment	Change of Plans
	Recompletion	New Construction
✓ Notice of Intent	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice Atlering Casing		Conversion to Injection
	✓ OTHER: RECOMPLETE TO GR	BRG Dispose Water  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*  TEXACO E&P INTENDS TO RECOMPLETE THE SUBJECT WELL TO THE GRAYBURG POOL. THE INTENDED PROCEDURE IS AS FOLLOWS:  1) MIRU MAST UNIT & LOGGING TRUCK. LOG 4900-2900 W/GR/CNL/CCL.  2) MIRUSU. INSTL BOP. PU WS & TIH W/CSG SCRAPER. C/O CSG TO 3700. PRESS TEST TO 1000 PSI.  3) PERF GRAYBURG FORMATION. INTERVALS TO BE PICKED OFF OF LOG RUN IN STEP #1.  4) TIH W/TBG & PKR. STOP 1 JT ABOVE TOP PERFORATION. PRESS TEST NLINES. LOAD HOLE W/2% KCL WTR.  5) PICKLE TBG BY PUMPING TWO 200 GAL SLUGS OF ACID DN TBG TO END.  6) SET PKR & RIG BACK TO TBG FOR ACID BREAKDOWN. ESTAB INJECTION RATE W/2% KCL WTR. ACIDIZE GRAYBURG W/20% HCL.  7) FLOW WELL BACK UNTIL DEAD.  8) TOH W/WS. TIH W/PRODUCTION STRING.  9) RDMOSU.  APPROVED FOR		
14. I hereby certify that the (pregoing in true and correct SIGNATURE J. Denise Le	TITLE Regulatory Specialist	DATE 6/13/2002
(This space for Federal or State office use)	SIGNEU DE	
TYPE OR PRINT NAME  J. Denise Le  (This space for Federal or State office use)  APPROVED  CONDITIONS OF APPROVAL, IF ANY:  Title 18 U.S.C. Section 1001, makes it a crime for any person knowing representations as to any matter within its jurisdiction.	E ORIGINAL F. KAUIZ PAUL F. KAUIZ PAUL F. KAUIZ	DATE JUL 3 1 2002
Title 18 U.S.C. Section 1001, makes it a crime for any person knowing representations as to any matter within its jurisdiction.	gly and willfully to make to a water and will a water a	States any false, fictitious or fraudulent statements or

BECEINED

2007 JUN 18 AM 8: 53

INEM CALLEGUA DA MENUR BOPPIO LIBINEOR

M. FI WIL