

RECEIVED

INSPECTION RECORD - ABANDONMENT

CRA

WELL NO. Gulf Fed. #1
AUG 27 8 14 AM '90
NWNW SEC. 20 T. 25 R. 35
CART. AREA Wild cat

OPERATOR Cowen Equipment Co.

LEASE NO. NMO 450818

TYPE OF WELL Gas Well

CONTRACTOR D, A & S

LOG ISSUED

COUNTY: LEA

STATE: NEW MEXICO

* DRY HOLE, CEMENTED PRODUCER, SERVICE, WATER WELL, ETC.

MECHANICAL PLUG PLACEMENT DATE CIBP set at 13,400'-8-14-90

Installed dry hole marker 8-24-90

CEMENT PLUG SPOTTING METHOD: BALANCE ☒ 2 PLUG ☐ BAILEY ☐

ADDITIONAL REMARKS Revised plugging program to include shoe plug.

Csg. cut at 5200' shoe at 5300' set 225' plug on shoe and stub together.

PLUG #1 13,400' TO 13,350' WITH 16 SACKS ~~TAG OR TEST~~ Capped CIBP

PLUG #2 12080' TO 11930' WITH 60 SACKS ~~TAG OR TEST~~ balance

PLUG #3 9,524' TO 9,424' WITH 40 SACKS ~~TAG OR TEST~~ balance

PLUG #4 5350' TO 5155' WITH 100 SACKS TAG OR TEST 30' short

PLUG #5 5155' TO 5125' WITH 20 SACKS TAG OR TEST spot

PLUG #6 1050' TO 950' WITH 67 SACKS TAG OR TEST balance

PLUG #7 50' TO SURF. WITH 33 SACKS TAG OR TEST circulate

DATES (E) 8-13, 8-14, 8-15, 8-16, 8-17, 8-18, 8-19, 8-20 INSPECTOR Andy Cortez / M.E. MANUS
8-23-90-8-24-90

TOTAL TIME ON JOB 62 HRS. INCLUDES 20 HRS. TRAVEL 10 1/2 OVERTIME

	YES	NO	NA	ENT
Plugs spotted across perforations if casing set? ..		☒		S
Plug spotted at any casing steel?	☒			S
Plug hole plugs as specified?		☒		S
Mechanical plugs set as specified?	☒			S
Cement quantities as specified?	☒			S
Log tested as specified?	☒			S
Pipe withdrawal rate satisfactory?	☒			S
Plugs plugged to surface?	☒			S

FOR RECORD ONLY