

MIDLAND E & P DIVISION

WELL WORK RECOMMENDATIONS

Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: Humphrey Queen Unit Well No. 15-1111
Field: Laughe Matrix Comm
County: Lea State: New Mexico

RECOMMENDED PROCEDURE:

1. M.L.R.U.
2. Pull Cement lined tubing and packer.
3. Plug Back from 3650' TD to 3490' using Ottawa Sand
with a 10' Hydrumite Cap.
4. Run Cement lined tubing and packer.