ī

## UNI D STATES DEPARTMEN. OF THE INTERIOR (Other instructions verse side) GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC mE.

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

11'1 - 054031

SHNDRY	NOTICES	AND	<b>REPORTS</b>	ON	WELLS	
3011211	, , •				4.44	

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.)

7. UNIT AGREEMENT NAME WELL | OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR Cotton Draw Unit TEXACO IIIC. 9. WELL NO. 3. ADDRESS OF OPERATOR 73

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)
At surface P. O. Box 728 - Hobbs, New Mexico

10. FIELD AND POOL, OR WILDCAT Paduca Delaware North Gas 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Well is located 554' from the North line and 554' from the East line of Section 4.

Sec. 4, T-25-S, R-32-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3513' (DF)

12. COUNTY OR PARISH | 13. STATE

New Mexico

Lea

Regular

TEST WATER S FRACTURE TRE. SHOOT OR ACIE REPAIR WELL

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

			SUBSEQUENT REPORT OF:	
NOTICE OF INTENTION TO:				
HUT-OFF		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)	
	C11/11/12	(Now: Report results of multiple completion on We	511	

Completion or Recompletion Report and Log form.) (Other) COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-17. DESCRIBE PROPOSED OR COMPLETED OPERA' proposed work. If well is directiona pent to this work )\* proposed work. In nent to this work.)

## REMARKS

- Well Status ASD-NG (Abandoned Salvage Deferred-Natural Gas) ٦.
- Temporary Abandonment Date December 4, 1975 2.
- Reason for Abandonment Low gas production makes well uneconomical 3. to produce.
- Future Plans Plug and Abandon
- Date of Future Workover or Plugging 1976

JAN 1 1977 T-18 approval of temporary abandonment expires

18. I hereby certify that the foregoing is true and correct  $_{ extbf{TITLE}}$   $\Lambda$ sst. SIGNED (This space for Federal or State office y APPROVED BY CONDITIONS OF APPROVAL, IF ANY: