

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER- WIW	7. Unit Agreement Name Langlie Mattix Queen Unit
2. Name of Operator Mobil Producing TX & NM Inc.	8. Farm or Lease Name
3. Address of Operator 9 Greenway Plaza, Suite 2700, Houston, TX 77046	9. Well No. 25
4. Location of Well UNIT LETTER P 990 FEET FROM THE east LINE AND 330 FEET FROM THE south LINE, SECTION 15 TOWNSHIP 25-S RANGE 37-E NMPM.	10. Field and Pool or Wildcat Langlie Mattix/ 7 Rivers Queen
15. Elevation (Show whether DF, RT, GR, etc.) GR-3090	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- 7-10-86 GIH w/ 33 jts 2-7/8 WS, rel RBP @ 1013' & POH; GIH w/ 100 jts 2-7/8 tbq, tag sd on top of RBP @ 3100', disp. hole w/ 75 bbls 9.5#/gal. mud, SIFN.
- 7-11-86 Mix 3 sx Class C cmt, RIH to 3100', dump from 3100' - 3076', POH; GIH w/ 41 jts 2-7/8 WS + 5 1/2 CIBP, set @ 1274', POH w/ WS; RIH w/ perf gun & perf 5 1/2 csg w/ 4 holes from 1255' - 1258', POH w/ gun; RIH w/ 5 1/2 cmt. ret., set @ 1150'; BJ mix & pump 90 sx Class C cmt; LD 2-7/8 WS & stinger, mix & pump 10 sx Class C cmt as surface plug, cut off 5 1/2 csg, weld on plate, install P&A marker.
Mr. R.A. Sadler (NMOCD) came out to location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Donna Mayes TITLE Authorized Agent DATE 10-13-86

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: