	CO'	PY TO O. C. C			
Form 9-331 (May 1963)	UNIT' STATES DEPARTMENT OF THE INTE GEOLOGICAL SURVEY	SUBMIT IN TRIPLIC (Other instructions of RIOR verse side)	Form approve Budget Burea 5. LEASE DESIGNATION LC 05554	u No. 42-R1424. And Serial NO.	
	INDRY NOTICES AND REPORTS this form for proposals to drill or to deepen or plu Use "APPLICATION FOR PERMIT_" for suc		6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
1. OIL GAS WELL GAS WEL 2. NAME OF OPERATOR		Nell MAR 5 1981	7. UNIT AGREEMENT NAM Langlie 8. Farm or lease nam	Jal	
Union Te:	xas Petroleum Corp	Langlie Jal Unit			
3. ADDRESS OF OPERA 1300 Will	co Bldg, Midland, TX 79701		9. WELL NO. 47		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter "F", 1980' FNL & 1885' FWL			10. FIELD AND POOL, OR WILDCAT Langlie -Jal Mattix (Queer 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Sec 5, T-25-S, R-37-E		
14. PERMIT NO.	15. ELEVATIONS (Show whethe	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE	
	3242' GR		Lea	New Mexico	
16. W	Check Appropriate Box To Indicate	· · · ·	Other Data QUENT REPORT OF:		
TEST WATER SHU	T-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	ELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	SING	
SHOOT OR ACIDIZI	E XX ABANDON*	SHOOTING OR ACIDIZING	ARANDON HER		
REPAIR WELL	CHANGE PLANS	(Other)			
(Other)		Completion or Recom	s of multiple completion of pletion Report and Log for	<u>"1001</u>	
17. DESCRIBE PROPOSE proposed work. nent to this wor	D OR COMPLETED OPERATIONS (Clearly state all perti If well is directionally drilled, give subsurface k.)*	inent details, and give pertinent dates locations and measured and true vertions			
Approxima	te date of proposed work is Ma	rch 25, 1981.		HCAL SURVEY EW MEXICO	

Approval is requested to acidize the subject well in order to remove permeability damage resulting from iron sulfide plugging of the injection interval. The well ceased to take injection in August of 1980. A recent coiled tubing clean out only improved injection to 20 BWPD. Well No. 47 is located in the highest cumulative recovery of the LJU and cannot be allowed to cease injection or recovery will be significantly reduced. Payqut is based on increasing production 10 BOPD in offset wells and will result in less than one month following a 4 month response period.

Offset injectors are taking from 197 - 321 BWPD with injector pressure for these wells running from 750 - 810 psi. Therefore, since tubing pressure of this well is 750 psi and the well is taking only 20 BWPD it is recommended this well be acidized to increase injectivity.

I hereby certify that the foregoing is true and co SIGNED Frieda M. Camp		St DATE 3-2-81
(This space for Federal or State office use)		APPROVED
APPROVED BY CONDITIONS OF APPROVAL, IF ANY :	TITLE	DATE
		LAAR 1 0 1981
	*See Instructions on Reverse Side [,]	JAMES A. GILLHAM D: TRICT SUPERVISOR