

U. S. GEOLOGICAL SURVEY
P. O. Box 1157
Hobbs, New Mexico 88240

Re: Permanent Abandonment

Well: 1 RAF 30

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Hobbs office (telephone (505) 393-3612 is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. Surface restoration after abandonment is to be in accordance with the operator-surface owner agreement unless otherwise advised.
5. Place additional 25 sack cement plug in interval 6000-6200 feet.