

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1434

5. LEASE DESIGNATION AND SERIAL NO.

LC 067968

6. IF NOT AN INDIAN ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

RAF 30

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Dollarhide (Devonian)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

30-24S-R38E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

HNG OIL COMPANY

3. ADDRESS OF OPERATOR

P.O. Box 2267-Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Letter J; 1750 FSL & 2100 FEL of
sec. 30, T 24S, R 38E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GL 3130

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-2-76 Rigged up, clean out cellar

6-24-76 Pulled tubing, set 4½" BP @ 7700'w/3 sx. cmt. on top

6-25-76 Spotted 25 sx. plug (5680'-6000').

6-28-76 Shoot 4½" csg. @ 2665'-laid down 68 Jts. 4½" csg.

6-29-76 Spot 50 sx. plug (2465'-2740'), 30 sx. plug (1070'-1200'),
and 10 sx. plug at surface, install dry hole marker.

ABANDONMENT - THIS
WELL ABANDONED ORALLY BY
OCC AND ~~OTHER~~ PLUGGING
WITNESSED BY NIA OCC REPRESENTATIVE BROWN
BEFORE WE APPROVED THE NIA

NOTED

15

B.P. OK
(P)

18. I hereby certify that the foregoing is true and correct

SIGNED

R. R. Frazier

TITLE Dist. Prod. Supt.

DATE 7-9-76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 10 1977

BERNARD MOROZ
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side