Submit 3 Copies To Appropriate District	State of New Mexico				D	Form C-103 rised March 25, 1999	
Office District 1	gy, Minerals and Natural Resources			WELL API N		rised March 23, 1999	\neg
1625 N. French Dr., Hobbs, NM 87240 District II				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		30-025-24168	
811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION			5. Indicate Type of Lease			
istrict III 2040 South Pacheco 900 Rio Brazos Rd., Aztec, NM 87410 South Pacheco			STATE FEE X				
District IV 2040 South Pacheco, Santa Fe, NM 87505				6. State Oi	l & Gas Le	ase No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:				7. Lease Nai SOUTH JU	me or Unit STIS UNI	Agreement Nam T "G"	ıe
On wen Es Gas wen Es				8. Well No.	13		
2. Name of Operator HENRY PETROLEUM LP							
3. Address of Operator 3525 ANDREWS HWY MIDLAND TX 79703-5000				Pool name or Wildcat JUSTIS-BLBRY-TUBB-DRINKARD			
4. Well Location							
Unit Letter J	· 1750 feet from the	SOUTH	line and <u>231</u>	fe	et from the	EAST 1	ine
Section 12	Township25S	Rai	nge 37E	NMPM	Со	untyLEA	
Beeton 12	10. Elevation (Show who 3091 GR		RKB, RT, GR, etc.)				
11 Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO:				SEQUENT	KEPU	RT OF: .TERING CASIN	c \square
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	KK.		TERING CASIN	<u> Б</u>
TEMPORARILY ABANDON	X CHANGE PLANS		COMMENCE DR	RILLING OPNS	i.□ Pl Af	LUG AND BANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST A CEMENT JOBS	ND			
OTHER:			OTHER:				
12. Describe proposed or comp of starting and proposed we or recompletion.1) PULL OUT OF HOLE WIT	ork). SEE RULE 1103. For N	Multiple C	tinent details, and Completions: Attac	give pertinent h diagram of p	dates, incloroposed c	luding estimated ompletion	date
2) RUN GAUGE RING ON SA	AND LINE IF NECESSARY	<i>7</i> .					
3) RUN CIBP ON TUBING AND SET AT 5100' (75" ABOVE TOP PERFORATION)							
4) LOAD HOLE & PRESSUR	E TEST TO 500 PSI FOR M	MIT TEST					
5) LOAD HOLE WITH INHII							
6) PULL AND LAY DOWN A	ALL EQUIPMENT TO TA \	WELL.					
I hereby certify that the inform	nation above is true and comp	plete to the	e best of my know	ledge and beli	ef.		
SIGNATURE Soy		,	REGULATORY			DATE 08/01/20	01
Type or print nameROY R. JO	OHNSON				Telepho	one No. (915)694	4-3000
	7kH 10011						
(This space for State use)						DATELL	
APPROVED BY		TITLE_				DATE	
Conditions of approval, if any	/:						