NO. OF COPLES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
ANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
ILE		5a. Indicate Type of Lease
		State Fee. X
AND OFFICE	·	5. State Oil & Gas Lease No.
PERATOR		
	ANOTICES AND DEDODTS ON WELLS	
DUNUK I DO NOT USE THIS FORM FOR PROP	Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different reserve on for permit -** (form C-101) for such proposals.)	
USE **APPLICATIO	In FOR PERMIT - (FORM CHECK) - CA	7. Unit Agreement Name
OIL CAS WELL	OTHER-	
Name of Operator		8. Form or Lease Name
John H. Hill		Harrison
Address of Operator		9. Well No.
	, Suite 100, Aústin, Texas 78701	
Location of Well	, Dailee 100, Habetin, 10Hab 10102	10. Field and Pool, or Wildcat
	660 FEET FROM THE NOrth LINE AND 860	_ FEET FROM Langlie Mattix
UNIT LETTER	FEET FROM THELINE AND	
East	7 TOWNSHIP 255 RANGE 37E	NMPM. ())))))))))))))))))))))))))))))))))))
THELINE, SECTIO	N TOWNSHIP RANGE TOWNSHIP	
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3191 K. B.	Lea
	IIIII	port or Other Data
6. Check A NOTICE OF IN	Appropriate Box To Indicate Nature of Notice, Report of Notice, Re	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS	. X PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT	mulation
	OTHER DU	
OTHER		
OTHER	(Q) is seen to a price of the section of the sectio	es, including estimated date of starting any proposed
7 Describe Proposed or Completed Or	perations (Clearly state all pertinent details, and give pertinent dat	es, including estimated date of starting any proposed
17. Describe Proposed or Completed Op work) SEE RULE 1103.	CORRECTED	
7. Describe Proposed or Completed OF work) SEE RULE 1103. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	perguons (Clearly state all pertinent details, and give pertinent data CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed OF work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act	CORRECTED Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Vater fraced w/40,000#
7. Describe Proposed or Completed Op work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act 20-40 sand and 30	Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-v 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Mater fraced w/40,000# Preparing to put on pump.
17. Describe Proposed or Completed Of work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sh 4 1/2" casing to w/ 12 holes. Act 20-40 sand and 30	Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-v 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Mater fraced w/40,000# Preparing to put on pump.
17. Describe Proposed or Completed Of work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act 20-40 sand and 30	Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Mater fraced w/40,000# Preparing to put on pump.
17. Describe Proposed or Completed Of work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act 20-40 sand and 30	Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Mater fraced w/40,000# Preparing to put on pump.
17. Describe Proposed or Completed Of work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act 20-40 sand and 30	Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-v 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Mater fraced w/40,000# Preparing to put on pump. Preparing to put on pump.
17. Describe Proposed or Completed Op work) SEE RULE 1103. Class C, cement of to 700 #. Drilled 0 3636' w/325 sl 4 1/2" casing to w/ 12 holes. Act 20-40 sand and 30	Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-w 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Mater fraced w/40,000# Preparing to put on pump. Preparing to put on pump.
17. Describe Proposed or Completed Of work) SEE RULE 1103. Spudded 12-8-73. Class C, cement of to 700 #. Drilled @ 3636' w/325 sh 4 1/2" casing to w/ 12 holes. Act 20-40 sand and 30	Drilled 11" hole, set 8-5/8", 24# circulated. WOC 12 hrs, pressure d 7-7/8" hole to 3642'. Set 4-1/2 ks 50/50 Posmix and Class C. WOC 3000#. Perforated Seven Rivers - idized w/1000 g. 15% acid. Sand-v 0,000 gals. gelled fresh water. H	J-55 casing @ 353' w/175 sk tested casing and BOP 2", 9.5# K-55 casing 26 days. Pressure tested Queen 3257 to 3513 Mater fraced w/40,000# Preparing to put on pump. Preparing to put on pump.