

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
JUN 27 1991
O. S. ...
ARTESIA, N.M.

WELL API NO. 30-025-24627
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. NM 800R
7. Lease Name or Unit Agreement Name EATON NW JH
8. Well No. 15
9. Pool name or Wildcat JUSTIS BLINEBRY

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	4. Well Location Unit Letter C : 990 Feet From The NORTH Line and 1650 Feet From The WEST Line Section 12 Township 25S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3108.8' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR WATER FLOOD PROJECT

6/19/91 LAY DOWN RODS & PUMP. REMOVE WELL HEAD, NU BOP. TAG CIBP @ 5660'. POOH w/ TBG. START IN HOLE w/CIBP. STOPPED AT ± 1700'. WIRELINE PARTED.

6/20/91 PU WIRELINE GRAPPLE, BUMPER SUB, HYDRAULIC JARS & 6 3-1/2" DC's. GIH. TOP OF FISH @ 4816'. RECOVERED 650' WIRELINE.

6/21/91 GIH w/OVERSHOT, BUMPER SUB, HYDRAULIC JARS, 6 DC's & TBG. FISH AT 5650'. RECOVERED ROPE JOCKET, COLLAR LOCATED, SETTING TOOL & CIBP. RIH w/BIT, CSG SCRAPPER.

6/24/91 RUN GAUGE RING & JUNC BASKET ON WIRELINE TO 5150'. SET CIBP ON WIRELINE @ 5100'. RIH w/TBG TO CIBP. CIRCULATE HOLE w/TREATED PKR FLUID.

- 6/24/91 LAY DOWN TBG. RD BOP, RU WELL HEAD w/1 JT TBG IN WELL HEAD. FILL HOLE w/TREATED PKR FLUID. PRESSURE TEST CIBP TO 350# 30 MINS, OK. CIBP SET @ 5100'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 6/26/91

TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: This Approval of Temporary Abandonment Expires 7-1-96

