]	1		
ND. OF COPIES RECEIVED			
DISTRIBUTION			Form C-103 Supersedes Old
ANTA FE	NEW NEXICO OU CON		C-102 and C-103
ILE	NEW MEXICO UL CONS	ERVATION COMMISSION	Effective 1-1-65
.s.g.s.			
			Sa. Indisate Type of Lease
ERATOR			State XX Fee
			5. State Oil & Gas Lease No.
SUNDOM	NOTICES AND DEDODTS OF		
(DO NOT USE THIS FORM FOR PROPOSI USE "APPLICATION	NOTICES AND REPORTS ON TALS TO DRIVE ON TO DEEPEN OF PLUG FOR PLANTE - FORM C-1011 FOR SUC	WELLS ACK TO A DIFFERENT RESERVOIR. H FROPOSALS.)	
OIL X CAS WELL	OTHER-		7. Unit Agreement Nume Langlie-Jal Unit
NION TEXAS PETROLEUM CO	RPORATION		8. Farm or Lease Name
diress of Operator 300 Wilco Building, Mid	land, Texas 79701		9. Well No. 2
ocation of Well			10. Field and Pool, or Wildcat
UNIT LETTER <u>A</u> 991	FEET FROM THE North	LINE AND 660 FEET	FROM Langlie-Mattix (Queen
THE East LIKE, SECTION _			MPM.
	15. Elevation (Show whether 3240.5' GR	DF, RT, GR, ctc.)	12. County Lea
Charles Apr	A A A A A A A A A A A A A A A A A A A		
NOTICE OF INTE	propriate Box To Indicate N ENTION TO:		Other Data ENT REPORT OF:
ORM REMEDIAL WORK	PLUG AND ABANDON		
CRARILY ABANDON	FLOG AND ASANDON	REMEDIAL WORK	ALTERING CASING
OR ALTER CASING	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	CBARGE PLANS	CASING TEST AND CEMENT JOB	Anidia
THER		OTHER	Acidize
• •			
	ions (Clearly state all pertinent deta	ils, and give pertinent dates, inclu	ding estimated date of starting any propose
escribe Proposed or Completed Operat ork) SEE RULE 1103.	•		
			•
May 8, 1977, RU and 1	e-entered well. Pulle	d production tubing a	nd rods.
May 8, 1977, RU and r Ran tubing and set tu	e-entered well. Pulle	d production tubing a d 150 gals 15% BJ Aci	nd rods. d.
May 8, 1977, RU and r Ran tubing and set tu	e-entered well. Pulle	d production tubing a d 150 gals 15% BJ Aci	nd rods. d.
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e-entered well. Pulle bing at 3560'. Spotte perforations with 2,0	d production tubing a d 150 gals 15% BJ Aci 00 gals 15% iron stab	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages. May 10, 1977, Ran pro	re-entered well. Pulle bing at 3560'. Spotte perforations with 2,0 duction tubing, rods,	d production tubing a d 150 gals 15% BJ Aci DO gals 15% iron stab & pump. Placed well	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages. May 10, 1977, Ran pro	re-entered well. Pulle bing at 3560'. Spotte perforations with 2,0 duction tubing, rods,	d production tubing a d 150 gals 15% BJ Aci DO gals 15% iron stab & pump. Placed well	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages. May 10, 1977, Ran pro	e is true and complete to the best of	d production tubing a d 150 gals 15% BJ Aci DO gals 15% iron stab & pump. Placed well	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages.	e is true and complete to the best of	d production tubing a d 150 gals 15% BJ Aci DO gals 15% iron stab & pump. Placed well	nd rods. d. ilized acid in four
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages. May 10, 1977, Ran pro	e is true and complete to the best of	d production tubing a d 150 gals 15% BJ Aci DO gals 15% iron stab & pump. Placed well	nd rods. d. ilized acid in four back on production
May 8, 1977, RU and r Ran tubing and set tu May 9, 1977, Acidized 500 gallon stages. May 10, 1977, Ran pro	e is true and complete to the best of	d production tubing a d 150 gals 15% BJ Aci DO gals 15% iron stab & pump. Placed well	nd rods. d. ilized acid in four back on production



MAY 13 1977 UL CONSENTION COMM. HOBBS, N. M. .