TEST WATER SHUT-OFF       PULL OR ALTER CASING       WATER SHUT-OFF       X         FRACTURE TREAT       MULTIPLE COMPLETE       FRACTURE TREATMENT       X         SHOOT OR ACIDIZE       ABANDON*       SHOOTING OR ACIDIZING       X         REPAIR WELL       CHANGE FLANS       (Other)       (Other)	SNT REPORT OF: REPAIRING WELL ALTERING CASING ABANDONMENT* f multiple completion on Well tion Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
I.       Use "APPLICATION FOR PERMIT_" for such proposals.)         I.       OTL       WELL         OIL       WELL       OTHER         2.       NAME OF OPERATOR       OTHER         2.       NAME OF OPERATOR       OTHER         2.       NAME OF OPERATOR       P. O. Drawer A, Levelland, Texas 79336         4.       LOCATION OF WELL (Report location clearly and in accordance with any State requirements."         3.       Aboress of OPERATOR         P. O. Drawer A, Levelland, Texas 79336         4.       LOCATION OF WELL (Report location clearly and in accordance with any State requirements."         At surface       15.         1535' FNL x 330' FEL (Unit H, Sec.22)         14.       PERMIT NO.         15.       PLEVATIONS (Show whether DF, RT, GR, etc.)         3223.8 GR       GR         16.       Check Appropriate Box To Indicate Nature of Notice, Report, or O         NOTICE OF INTENTION TO:       SUBSEQUE         TEST WATER SHUT-OFF       PULL OR ALTER CASING         WATER SHUT-OFF       PULL OR ALTER CASING         WULTIPLE COMPLETE       SHOOTING OR ACIDIZING         (Other)       Completion or Recomplete         (Other)       Completence of ONTERT OFERATIONS (Clearly state all pertiment details, and zive pertiment dates, I	6. IF INDIAN, ALLOTTEE OR TRIBE NAME         7. UNIT AGREEMENT NAME         South Mattix Unit         8. FARM OR LEASE NAME         South Mattix Unit         9. WELL NO.         32         10. FIELD AND FOOL, OR WILDCAT         Wildcat McKee         11. SEC., T., E., M., OR BLE. AND         SURVEY OR AREA         22-24-37         12. COUNTY OR PARISH         13. STATE         Lea         NM         ther Data         ENT REPORT OF:         REPAIRING WELL         ALTERING CASING         ALTERING CASING         ABANDONMENT*         f multiple completion on Well         thor Report and Log form.)         ncluding estimated date of starting any         depths for all markers and zones perti-         5. 5# K-55 LT&C casing         ASS H. Circulate coment
OIL       WELL       GAS         WELL       OTHER         2. NAME OF OPERATOR       AMDOCO Production Company         3. ADDRESS OF OPERATOR       P. O. Drawer A, Levelland, Texas 79336         4. Location of well. (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface         15.35'       FNL x 330'         16.       Check Appropriate Box To Indicate Nature of Notice, Report, or O NOTICE OF INTENTION TO:         Stee also close       SUBSEQUI         16.       Check Appropriate Box To Indicate Nature of Notice, Report, or O NOTICE OF INTENTION TO:         SHOOT OR ACIDIZE REPARE WELL       PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANCE PLANS         17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i nent to this work.)'         17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i nent to this work.)'         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 650 sx Howcolite and 1/4#1sx	South Mattix Unit 8. FARM OR LEASE NAME South Mattix Unit 9. WELL NO. 32 10. FIELD AND FOOL, OR WILDCAT Wildcat McKee 11. SPC., T., E., M., OR BLK. AND SURVEY OR AREA 22-24-37 12. COUNTY OR PARISH Lea NM ther Data SNT REPORT OF: REPAIRING WELL ALTERING CASING ABANDON MENT* of multiple completion on Well tion Report and Log form.) ncluding estimated date of starting any depths for all markers and zones perti- 5. 5# K-55 LT&C casing ass H. Circulate cement
2. NAME OF OPERATOR       AMOCO Production Company         3. ADDRESS OF OPERATOR       P. O. Drawer A, Levelland, Texas 79336         4. LOCATION OF WELL (Report location clearly and in accordance with aby State requirements.* See also space 17 below.) At surface         15.35' FNL x 330' FEL (Unit H, Sec.22)         14. PERMIT NO.         15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3223.8 GR         16.         Other Report of INTENTION TO: SUBSEQUING NOTICE OF INTENTION TO: TEST WATER SHUT-OFF, PRACTCHE TREAT SHOOT OR ACIDIZE REPARE WELL (Other)         FULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANCE FLANS         NOTICE OF INTENTION TO: SUBSEQUING (Other)         TEST WATER SHUT-OFF, PRACTCHE TREAT SHOOT OR ACIDIZE REPARE WELL (Other)         FULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANCE FLANS         Continued drilling to Greenple operations (Clearly state all pertiment details, and give pertiment dates, for ment of this work.)*         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx C1 off DV tool. Cement 2nd stage with 650 sx How colite and 1/4#1sx	8. PARM OR LEASE NAME South Mattix Unit 9. WELL NO. 32 10. FIELD AND FOOL, OR WILDCAT Wildcat McKee 11. SPC., T., E., M., OR BLE. AND SURVEY OR AREA 22-24-37 12. COUNTY OR PARISH Lea NM ther Data ENT REPORT OF: REPAIRING WELL ALTERING CASING ABANDONMENT* f multiple completion on Well thon Report and Log form.) meluding estimated date of starting any depths for all markers and zouces perti- 5. 5# K-55 LT&C casing ass H. Circulate cement
3. ADDRESS OF OPERATOR         P. O. Drawer A, Levelland, Texas 79336         4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface         15.35' FNL x 330' FEL (Unit H, Sec.22)         14. PERMIT NO.         15. ELEVATIONS (Show whether DF, RT, GR, etc.)         3223.8 GR         16.         Check Appropriate Box To Indicate Nature of Notice, Report, or O         NOTICE OF INTENTION TO:         SUBSEQUI         FRACTURE TREAT         NULTIFLE COMPLETE         ABANDON*         Check Appropriate Box To Indicate Nature of Notice, Report, or O         NOTICE OF INTENTION TO:         SUBSEQUI         VATER SHUT-OFF         FULL OR ALTER CASING         MULTIFLE COMPLETE         ABANDON*         Check Appropriate DOPERATIONS (Clearly state all pertinent details, and give pertinent dates, i         (Other)         (Other)         Completion or Recomple         Operational completion of Permations (Clearly state all pertinent details, and give pertinent dates, i         TEST WATER ENDODOSED OR COMPLETED OPERATIONS (Clearly sta	South Mattix Unit 9. WELL NO. 32 10. FIELD AND FOOL, OR WILDCAT Wildcat McKee 11. SPC., T., E., M., OR BLK. AND SURVEY OR AREA 22-24-37 12. COUNTY OR PARISH 13. STATE Lea NM ther Data SNT REPORT OF: REPAIRING WELL ALTERING CASING ABANDON MENT* f multiple completion on Well thon Report and Log form.) ncluding estimated date of starting any depths for all markers and zones perti- 5. 5# K-55 LT&C casing ass H. Circulate cement
P. O. Drawer A, Levelland, Texas 79336 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface 1535' FNL x 330' FEL (Unit H, Sec.22) 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3223.8 GR 6. Check Appropriate Box To Indicate Nature of Notice, Report, or O NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESCRIBE PROPERED OR COMPLETED OPERATIONS (Clearly state all pertiment details, and give pertiment dates, 1 works of the directionally drilled, give subsurface locations and measured and true vertical Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx sonite and 8#/sx CACL + 1000 cx Chapter of Complete and 1/4#1sx	9. WELL NO. 32 10. FIELD AND FOOL, OR WILDCAT Wildcat McKee 11. SPC., T., E., M., OR BLK. AND SURVEY OR AREA 22-24-37 12. COUNTY OR PARISH Lea NM ther Data ENT REPORT OF: REPAIRING WELL ALTERING CASING ABANDONMENT* of multiple completion on Well tion Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5. 5# K-55 LT&C casing ass H. Circulate cement
A. DOCATION OF WELL (Report location clearly and in accordance with any State requirements.*         At surface         1535' FNL x 330' FEL (Unit H, Sec.22)         (4. PERMIT NO.         15. ELEVATIONS (Show whether DF, RT, GR, etc.)         3223.8 GR         6.         Check Appropriate Box To Indicate Nature of Notice, Report, or O         NOTICE OF INTENTION TO:         TEST WATER SHUT-OFF,         FRACTCRE TREAT         SHOOT OR ACIDIZE         BEPAIR WELL         (Other)         (Other)         7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent datas, i ment to this work.)*         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1         set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI         off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	10. FIELD AND POOL, OR WILDCAT         Wildcat McKee         11. SEC., T., E., M., OR BLK. AND         SURVEY OR AREA         22-24-37         12. COUNTY OR PARISH         13. STATE         Lea         NM         there Data         SURVEY OR PARISH         IS. STATE         Lea       NM         there Data         SURVEY OR FARISH         IS. STATE         Lea       NM         there Data         SURVEY OR FARISH         IS. STREPORT OF :         REPAIRING WELL         ALTERING CASING       ABANDONMENT*         Ion Report and Log form.)       neluding estimated date of starting any depths for all markers and zones perti-         5. 5# K-55 LT&C Casing       ass H. Circulate coment
14. PERMIT NO.       15. ELEVATIONS (Show whether DF, RT, GR, etc.)         3223.8 GR         6.       Check Appropriate Box To Indicate Nature of Notice, Report, or O         NOTICE OF INTENTION TO:         SUBSEQUE         TEST WATER SHUT-OFF         PULL OR ALTER CASING       WATER SHUT-OFF         PULL OR ALTER CASING       WATER SHUT-OFF         FRACTURE TREAT       MULTIPLE COMPLETE         SHOOT OR ACIDIZE       ABANDON*         COther)       CHANGE PLANS         (Other)       (NOTE: Report results of Completion or Recomple         Opposed work. If well is directionally drilled, give subsurface locations and measured and true vertical measured and 200 sx CI off DV tool. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	Wildcat McKee         11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA         22-24-37         12. COUNTY OR PARISH Lea         13. STATE Lea         NM         ther Data         SINT REPORT OF:         REPAIRING WELL ALTERING CASING ABANDONMENT*         of multiple completion on Well thon Report and Log form.)         ncluding estimated date of starting any depths for all markers and zones perti-         5. 5# K-55 LT&C casing ass H. Circulate cement
4. PERMIT NO.       15. ELEVATIONS (Show whether DF, BT, GR, etc.)         3223.8 GR         6.       Check Appropriate Box To Indicate Nature of Notice, Report, or O         NOTICE OF INTENTION TO:         SUBSEQUI         TEST WATER SHUT-OFF         FRACTURE TREAT       PULL OR ALTER CASING         MULTIPLE COMPLETE       WATER SHUT-OFF         ABANDON*       SHOOTING OR ACIDIZING         (Other)       CHANGE PLANS         (Other)       (NOTE: Report results of Completion or Recomple         Describe PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent dotails, and give pertinent dates, i nent to this work.)*         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1         Set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	22-24-37 12. COUNTY OR PARISH 13. STATE Lea NM ther Data ENT REPORT OF: REPAIRING WELL ALTERING CASING ABANDONMENT* f multiple completion on Well thon Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5. 5# K-55 LT&C casing ass H. Circulate cement
6. Check Appropriate Box To Indicate Nature of Notice, Report, or O NOTICE OF INTENTION TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Completion or Recomplete DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx C1 off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	12. COUNTY OR PARISH       13. STATE         Lea       NM         ther Data       NM         ENT REPORT OF:       Image: Completion of the state o
6. Check Appropriate Box To Indicate Nature of Notice, Report, or O NOTICE OF INTENTION TO: TEST WATER SHUT-OFF, PULL OR ALTER CASING FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) T. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx C1 off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	Lea NM ther Data SNT REPORT OF: REPAIRING WELL ALTERING CASING ABANDONMENT* of multiple completion on Well tion Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
Check Appropriate Box To Indicate Nature of Notice, Report, or O NOTICE OF INTENTION TO: TEST WATER SHUT-OFF, FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx C1 off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	ther Data SNT REPORT OF: REPAIRING WELL ALTERING CASING ABANDONMENT* of multiple completion on Well tion Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
NOTICE OF INTENTION TO:         SUBSEQUE         TEST WATER SHUT-OFF,         FRACTURE TREAT       PULL OR ALTER CASING         MULTIPLE COMPLETE       FRACTURE TREATMENT         SHOOT OR ACIDIZE       ABANDON*         (Other)       CHANGE FLANS         MULTIPLE COMPLETE       SHOOTING OR ACIDIZING         (Other)       Change Flans         (Other)       (Note: Report results of Completion or Recomple         Proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)*         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1         set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx         sonite and 8#/sx CACL + 1000 sx Class 0	ALTERING WELL ALTERING CASING ABANDONMENT* f multiple completion on Well tion Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
TEST WATER SHUT-OFF       PULL OR ALTER CASING         FRACTURE TREAT       MULTIPLE COMPLETE         SHOOT OR ACIDIZE       ABANDON*         COther)       CHANGE FLANS         * DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i nent to this work.)*         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	REPAIRING WELL ALTERING CASING ABANDONMENT* f multiple completion on Well tion Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
SHOOT OR ACIDIZE       ABANDON*         REPAIR WELL       CHANGE FLANS         (Other)       CHANGE FLANS         'DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i nent to this work.)*         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx C1 off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx	ALTERING CASING ABANDONMENT* f multiple completion on Well tion Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
REPAIR WELL       CHANGE PLANS       SHOOTING OR ACIDIZING         (Other)       (Other)       (Other)         DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, i nent to this work.)*       (Other)         Continued drilling to TD of 9707' on 2/27/78. Ran 5½" 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx sonite and 8#/sx CACL + 1000 sx Classe C	f multiple completion on Well the Report and Log form.) neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
(Other) (NOTE: Report results of Completion or Recompletion or Recom	neluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical Continued drilling to TD of 9707' on 2/27/78. Ran $5\frac{1}{2}$ " 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx Cl off DV tool. Cement 2nd stage with 200 sx Howcolite and 1/4#1sx sonite and 8#/sx CACL + 1000 sx Class C	ncluding estimated date of starting any depths for all markers and zones perti- 5.5# K-55 LT&C casing ass H. Circulate cement
Continued drilling to TD of 9707' on $2/27/78$ . Ran $5\frac{1}{2}$ " 17# and 1 set at 9707'. Cement 1st stage with 650 sx Filler and 200 sx CI off DV tool. Cement 2nd stage with 200 sx Howcolite and $1/4\#1sx$ sonite and $8\#/sx$ CACL + 1000 sx Class C	5.5# K-55 LT&C casing ass H. Circulate cement
Waiting on service unit.	d 6#/sx CACL. Plugged
	128 <b>1 3 1978</b>
U. S. HO	GEOLOGICA SUBA - Ses, New Mixaco
. I hereby certify that the foregoing is true, and correct	
signed Kandy athing TITLE Asst. Administrative Anal	vst 2 10 70
(This space for Federal or State office use)	yst <sub>bate</sub> <u>3-10-78</u>
APPROVED BY TITLE	
CONDITIONS OF APPROVAL, IF ANY:	ACCEPTED FOR RECORD
U + 4 -USGS-H 1-Arco 1 -Div 1-Tenneco	Q.Q.L.
1 -Susp. 1-Conoco *See Instructions on Reverse Side	MAR 1 3 1978
1 - RC	$100.00$ $\pm$ $0.107.0$
	U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO