

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator JOHN YURONKA	8. Farm or Lease Name Harrison
3. Address of Operator 214 W. Texas, Suite 1009, Midland, Texas 79701	9. Well No. #2
4. Location of Well UNIT LETTER <u>D</u> <u>330</u> FEET FROM THE <u>West</u> LINE AND <u>990</u> FEET FROM THE <u>North</u> LINE, SECTION <u>29</u> TOWNSHIP <u>24-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or WHdcat Langlie Mattix SR Qu 66
11. Elevation (Show whether DF, RT, GR, etc.) 3287' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUS AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUS AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/26 - MIRU
7/27 - POH with rods & tubing. Set CIBP @ 3347'. GIH with tubing, spot 10 sacks on top unable to circ.
7/28 - Set CIBP @ 3300'. Unable to circ. Set CIBP @ 3000'. Spot 10 sacks on top, circ hole with 9.5# mud. POH to 310'. Mix 25 sacks from 310' - surf. Cut-off WH, install DHM. RDMO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Yuronka

TITLE Authorized Agent

DATE 8-11-88

APPROVED BY R. A. Luder

TITLE OIL & GAS INSPECTOR

DATE NOV 04 1991

CONDITIONS OF APPROVAL, IF ANY: