

### TEST

After nipping up on surface pipe, but before drilling out the cement plug, the BOP's shall be tested to the rated working pressure.

### FREQUENCY

The BOP's shall be cycled on every trip.

