PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER:

State of New Mexico

Form C-103

ALTERING CASING

PLUG AND ABANDONMENT

Appropriate District Office	87,	Natural Resources	_		Revised 1-1-89
DISTRICT I O. Box 1980, Hobbs, NM 88240	OIL CONSER	VATION DI D. Box 2088	VISION [WELL API NO.	
DISTRICT II O. Drawer DD, Artesia, NM 88210		Mexico 87504	2088	30-025-26704 5. Indicate Type of Lease STAT	TE FEE X
DISTRICT III 000 Rio Brazos Rd., Aziec, NM 87410				6. State Oil & Gas Lease No.	
SUNDRY NO	TICES AND REPORTS	S ON WELLS			
(DO NOT USE THIS FORM FOR PE	7. Lease Name or Unit Agreement Name				
(FORM	J. W. Sherrell				
. Type of Well: OIL GAS WELL X	ОТНЕЯ	·			
Name of Operator				8. Well No.	
Doyle Hartman				10	
Address of Operator				9. Pool name or Wildcat	··>
•	idland, TX 79702	Jalmat (T-	Y-7R)		
4. Well Location					
Unit Letter C : 6	560 Feet From The	North	Line and 2	000 Feet From The	West Line
Section 6	Township 25-S	Range Show whether DF, RK		NMPM Lea	County
	///////	3236 GR	5, A1, GA, Esc./		
Check	k Appropriate Box to		e of Notice, R	eport, or Other Data	
	NTENTION TO:		SUB	SEQUENT REPOR	RT OF:
* - *		1			

REMEDIAL WORK

OTHER:

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUG AND ABANDON

CHANGE PLANS

Move in and rig up well service unit. Check PBTD and clean out if necessary. Pressure test casing as part of procedure for evaluating wellbore for rework potential. Repair casing if necessary.

I hereby certify that the infe	ormation above is true and coordinate to the best of	my knowledge and belief.		
SIONATURE Ta	tuit K. Wneel	TILE	Engineer	DATE9-07-91
	Patrick K. Worrell	•		TELEPHONE NO. $915-684-4011$
TYPE OR PRINT NAME	Tattick R. Wolfer			
(This space for State Use)	grag, algred by			· 9
APPROVED BY	Paul Kautz	тп.е		DATE —
CONDITIONS OF APPROVA	L, IF ANY:			