Orm 9-331         Ut         ED STATES         OFY         Official Calibration         ATE           May 1963)         DEPARTMELL         OF THE INTERIOR verse side)         a re-           GEOLOGICAL SURVEY         Contract Survey         Contract Survey					Form approved. Budget Bur-ru No. 42 R1424. 5. LEASE DESIGNATION AND NERIAL NO. NM 40658		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)					6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
1. OIL GAS WELL X WELL	OTHER				IT AGREEMENT NAME		
2. NAME OF OPERATOR				8. FA	RM OR LEASE NAME		
Alpha Twenty-One Production Company 3. ADDRESS OF OPERATOR					Buckskin Federal 9. WELL NO.		
2100 First Na	tional Bank Building	, Midland, I	'exas 79701	1			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. <sup>•</sup> See also space 17 below.) At surface					10. FIELD AND POOL, OR WILDCAT Dollarhide - Drinkard		
1980' FWL, 66	O' FSL, Sec. 18, T24	S, R38E		11. s	EC., T., R., M., OR BLK. A SURVEY OR AREA	IND	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, BT GR, etc.)					Sec. 18, T24S, R38E 12. COUNTY OF PARISH 13. STATE		
14. PERMIT NO.	3175 G.				ea	N. M.	
 16.			<u>Anna Anna Anna Anna Anna Anna Anna Anna</u>	+ <del>&gt;</del>			
	Check Appropriate Box 1	o Indicate Natur		,-or Other L			
	OTICE OF INTENTION TO:					[]	
TEST WATER SHUT-OF			WATER SHUT-OFF		REPAIRING WELL		
FRACTURE TREAT	MULTIPLE COMPLET	Б	FRACTURE TREATMENT SHOOTING OR ACIDIZIN		ALTERING CASING ABANDONMENT*	'	
SHOOT OR ACIDIZE REPAIR WELL	ABANDON* CHANGE PLANS		(Other) Casing			x	
(Other)			(NOTE: Report	results of mul	tiple completion on W leport and Log form.)	Vell	
17. DESCRIBE PROPOSED OF proposed work. If nent to this work.)	CONFLETED OPERATIONS (Clearly s well is directionally drilled, give	tate all pertinent des subsurface locations	ails and give rertinent	dates, includi	ing estimated date of	starting any i zones perti-	
with H Drilled	15" hole and set 30' Redimix to surface. 12¼" hole and set 12 emented with 700 sx. 80).	.95' of 8-5/8	3" 28 Lb. Grade	e B Surfa	ice Casing		
Drilled	7-7/8" hole and set	6825' of 5½'	' 17 Lb. J-55 H	roductic	n Casing as f	follows:	
One Flo 10. ★ DV	ide Shoe 9 Jt. 5½" Casing 0at Collar 2 Jts. 5½" Casing Tool Jts. 5½" Casing	1.30' 40.20' 1.50' 4,087.00' - 3.50' 2,691.50'					
Tot	al	6,825.00'					
<u>Second</u> 18. I hereby certify that بر	tage - 575 sx. Class Stage - 450 sx. Halli the foregoing is true and correct	burton Lite	nix. Circulat and 150 sx. C tive Vice Pres	lass_C_5( <i>I</i>	D-50 Pozmix.() Accomplished DATE 10-6-80	<u>dork</u> 10-5-80)	
SIGNED TOMMY (This space for Fede	Phipps eral or State office use)						
APPROVED BY CONDITIONS OF A	PPROVAL, IF ANY :	TITLE			DAFOR RECORD		
	*S	ee Instructions or	n Reverse Side		Ku	<i>.</i>	