	۰ــــــــــــــــــــــــــــــــــــ
For	mation Evaluation:
A.	Drilling Rate:
	1. The drilling rate shall be monitored with a geolograph from the surface
	to total depth.
	2
•	
в.	Well Cutting Samples:
	One set of well cutting samples shall be gathered every 10 feet from
•	the surface to total depth. Each sample is to be cleaned, bagged, and
	tagged and then grouped into bundles of ten samples per bundle with one
	bundle representating each 100-feet drilled.
•	state topresentating cach its feet drifted.
	· · · · · · · · · · · · · · · · · · ·

VIII.

-5-

•