

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division FORM APPROVED

1625 N. French Dr.
Hobbs, NM 88240

Budget Bureau No. 1004-0133
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM 40658
2. Name of Operator Lanexco, Inc.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 1105 West Kansas Jal, N.M. 88252	7. If Unit or C.A. Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) NE-SW S-18, T-24-S, R-38 E 1650 FSL & 1980 FWL	8. Well Name and No. Buckskin Federal #3
	9. API Well No. 30-025-2702500
	10. Field and Pool, or Exploratory Area Dollarhide Tubbs Drini
	11. County or Parish, State Lea, N.M.


12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

CIBP set at 4950' with 4 sacks cement on top
Circulate hole with salt gel and brine - 9#
Set 100 ft. cement plug from 2950' - 2850'
Set 100 ft. cement plug from 1300' - 1200'
Set 30 ft. plug in surface
Cut off wellhead and install dry hole marker
Remove all equipment and junk and rip up location and 1/4 mile of road



14. I hereby certify that the foregoing is true and correct		
Signed <u>Mike Cogdell</u>	Title <u>Production Supt</u>	Date <u>9-25-00</u>
(This space for Federal or State office use)		
Approved by _____	Title _____	Date _____
Conditions of approval, if any:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

*See Instruction on Reverse Side

3 GWW