

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27542
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name BATES
2. Name of Operator MERIDIAN OIL INC.	8. Well No. 3
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	9. Pool name or Wildcat JALMAT (GAS)
4. Well Location Unit Letter L : 1210 Feet From The WEST Line and 1635 Feet From The SOUTH Line Section 20 Township 25S Range 37E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3040.2 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-21-92 RIH TO 2735' W/ GUAGE RING. CSG FELT ROUGH. CALLED RAY SMITH W/ OCD, OK TO SET CIBP @ 2690'. RD WL. TIH W/ TBG & TAG CIBP. CIRC HOLE W/ MUD. CAP CIBP W/ 20 SX CLASS "C" CMT CONTAINING 2% CACL2. CALC TOP 2460'. PUH TO 1200', SPOT CMT PLUG W/ 15 SX CLASS "C" CMT CONTAINING 2% CACL2. CALC TOP 1075'. PUH TO 705', SPOT CMT PLUG W/ 15 SX CLASS "C" CMT CONTAINING 2% CACL2. CALC TOP 600'. PUH TO 50' FROM SURFACE, SPOT CMT PLUG BACK TO SURFACE, W/ 5 SX CLASS "C" CMT CONTAINING 2% CACL2. POOH W/ TBG. RDMOPU. WELL P&A'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roxann Scholz TITLE PRODUCTION ASST. DATE 6-25-92
TYPE OR PRINT NAME ROXANN SCHOLZ TELEPHONE NO. 915-688-6943

(This space for State Use)

APPROVED BY Charlie Lerman OIL & GAS INSPECTOR TITLE DATE AUG 16 1993
CONDITIONS OF APPROVAL, IF ANY: