

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

U.S. GEOLOGICAL SURVEY

P. O. BOX 1980

HOBBS, NEW MEXICO 88240
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032579 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Union Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Langlie Mattix-7R.Q.Gb

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 27 - T25S-R37E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
MORRIS R. ANTWEIL

3. ADDRESS OF OPERATOR
P. O. Box 2010, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1980' FNL & 330' FEL of Section 27

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3031.4 GR

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3375'; PBTD 3335'. Perforations 3217'-3311' (26 holes)

4½" Casing circulated to surface with cement

Proposed to Plug and Abandon as follows:

1. Spot 15 sk plug from 3335' to 3167' across perfs. *Tag plug*
2. Spot 15 sk plug from 451' to 300' across 8-5/8" casing shoe inside 4½" casing.
3. Spot 15 sk surface plug with marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 7/13/82

(This space for Federal or State use)

APPROVED BY (Signature) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 20 1982

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED

JUL 22 1962

O.C.H.
HOBBE OFFICE