Form 3160-5 (August 1999)

## UN11'ED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division FORM APPROVED OMB NO. 1004-0135

1625 N. French Dr. Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS NOTICES A			6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No			
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Oth		8. We		Well Name and No. RED HILL NORTH UNIT 901H		
2. Name of Operator Contact: BEV HA		BEV HATFIELD E-Mail: beverly_hatfield@eogre	esources.com	9. API Well No. 30-025-28003		
3a. Address P. O. BOX 2267 MIDLAND, TX 79702		3b. Phone No. (include area cod Ph: 915.686.3689 Fx: 915.686.3765	le)	10. Field and Pool, or RED HILLS; Bo		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		)		11. County or Parish, and State		
Sec 17 T25S R34E SWNE- <del>1986</del> FNL 1978FEL / <i>980</i>				LEA COUNTY, NM		
12. CHECK APPE	ROPRIATE BOX(ES) TO	) INDICATE NATURE OF	NOTICE, R	EPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION		ТҮРЕ С	OF ACTION	ACTION		
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Product	ion (Start/Resume)	☐ Water Shut-Of	
	☐ Alter Casing	☐ Fracture Treat	☐ Reclam	ation	■ Well Integrity	
☑ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomp	lete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Tempor	arily Abandon		
	Convert to Injection	Plug Back	g Back			
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit WO TO SET CIBP OVER 3RD 1-22-02 MI RU EUNICE WS: F	thy or recomplete horizontally, it will be performed or provide operations. If the operation restandonment Notices shall be file that inspection.)  DISONE SPRING; PULL 5 RAN 7 SET 5-1/2" 10K CI	the Bond No. on file with BLM/BI sults in a multiple completion or read only after all requirements, inclu	sured and true ve A. Required sul completion in a r iding reclamation	rtical depths of all pertir sequent reports shall be sew interval, a Form 316 1, have been completed,	nent markers and zones. filed within 30 days	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for full WO TO SET CIBP OVER 3RD 1-22-02 MI RU EUNICE WS; FCIBP @ 12,150' FOR A PBTD 1-23-02 ND WH; PULL 5-1/2" (1-27-02 RU HALLIBURTON; SPLUG FROM 8125 TO 8825'.	thy or recomplete horizontally, it will be performed or provide operations. If the operation resundonment Notices shall be file that inspection.)  DISONE SPRING; PULL 5 RAN 7 SET 5-1/2" 10K CII OF 12,115; CSG; ND CSG TOOLS TOOS TOOLS	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or re- ed only after all requirements, inclu 6-1/2 CSG; BP @ 12150'; TST TO 1000 IH W/2-7/8" TBG TO 8825'; SS H (0.2% HR5 & 0.3% CF	sured and true ve A. Required sul Completion in a r dding reclamation # - OK; DUM	rtical depths of all pertinosequent reports shall be see winterval, a Form 316 a, have been completed,	nent markers and zones. filed within 30 days. filed once and the operator has	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit WO TO SET CIBP OVER 3RD 1-22-02 MI RU EUNICE WS; FCIBP @ 12,150' FOR A PBTD 1-23-02 ND WH; PULL 5-1/2" (1-27-02 RU HALLIBURTON: S	thy or recomplete horizontally, it will be performed or provide operations. If the operation resundonment Notices shall be file that inspection.)  DISONE SPRING; PULL 5 RAN 7 SET 5-1/2" 10K CII OF 12,115; CSG; ND CSG TOOLS TOOS TOOLS	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or re- ed only after all requirements, inclu 6-1/2 CSG; BP @ 12150'; TST TO 1000 IH W/2-7/8" TBG TO 8825'; SS H (0.2% HR5 & 0.3% CF	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir usequent reports shall be new interval, a Form 316 a, have been completed, P 35' OF CMT ON PG; YIELD OF .94) DEUNICE WS; WEL	nent markers and zones. filed within 30 days 10-4 shall be filed once and the operator has  CMT  L SD,	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for full WO TO SET CIBP OVER 3RD 1-22-02 MI RU EUNICE WS; FCIBP @ 12,150' FOR A PBTD 1-23-02 ND WH; PULL 5-1/2" (1-27-02 RU HALLIBURTON; SPLUG FROM 8125 TO 8825'.	thy or recomplete horizontally, it will be performed or provide operations. If the operation resundonment Notices shall be file that inspection.)  DISONE SPRING; PULL 5 RAN 7 SET 5-1/2" 10K CII OF 12,115; CSG; ND CSG TOOLS TOOS TOOLS	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or re- ed only after all requirements, inclu 6-1/2 CSG; BP @ 12150'; TST TO 1000 IH W/2-7/8" TBG TO 8825'; SS H (0.2% HR5 & 0.3% CF	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir broadcast reports shall be used interval, a Form 316 a, have been completed, P 35' OF CMT ON PG; YIELD OF .94) DEUNICE WS; WEL	nent markers and zones. filed within 30 days 10-4 shall be filed once and the operator has  CMT  L SD,	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for full the strength of the transfer of the tr	hily or recomplete horizontally, the will be performed or provide operations. If the operation resonandonment Notices shall be file that inspection.)  DISONE SPRING; PULL 5 RAN 7 SET 5-1/2" 10K CIII OF 12,115; CSG; ND CSG TOOLS	give subsurface locations and meas the Bond No. on file with BLM/BI ults in a multiple completion or re- ed only after all requirements, inclu 6-1/2 CSG; BP @ 12150'; TST TO 1000 IH W/2-7/8" TBG TO 8825'; SS H (0.2% HR5 & 0.3% CF	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir sosequent reports shall be lew interval, a Form 316 a, have been completed, P 35' OF CMT ON PG; YIELD OF .94) DEUNICE WS; WEL	ent markers and zones. filed within 30 days 0-4 shall be filed once and the operator has  CMT L SD,	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for full the stream of the involved testing has been completed. Final Ab determined that the site is ready for full the stream of the stre	true and correct.	give subsurface locations and measure the Bond No. on file with BLM/BI tults in a multiple completion or read only after all requirements, included only after all requirements, included the subsurface of the su	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir sosequent reports shall be lew interval, a Form 316 a, have been completed, P 35' OF CMT ON PG; YIELD OF .94) DEUNICE WS; WEL	ent markers and zones. filed within 30 days of 30-4 shall be filed once and the operator has CMT_L SD,	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit WO TO SET CIBP OVER 3RD 1-22-02 MI RU EUNICE WS; FCIBP @ 12,150' FOR A PBTD 1-23-02 ND WH; PULL 5-1/2" (1-27-02 RU HALLIBURTON; SPLUG FROM 8125 TO 8825'. SWO ROTARY TOOLS.	true and correct.	give subsurface locations and measure the Bond No. on file with BLM/BI sults in a multiple completion or read only after all requirements, included only after all requirements, included the BP @ 12150'; TST TO 1000 IH W/2-7/8" TBG TO 8825'; SS H (0.2% HR5 & 0.3% CF 5 HRS; ND BOP & CAP WE	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir sosquent reports shall be seen winterval, a Form 316 a, have been completed,  P 35' OF CMT ON  PG; YIELD OF .94)  EUNICE WS; WEL  CEPTED FOR	ent markers and zones. filed within 30 days of 30-4 shall be filed once and the operator has CMT_L SD,	
Attach the Bond under which the word following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit WO TO SET CIBP OVER 3RD 1-22-02 MI RU EUNICE WS; FCIBP @ 12,150' FOR A PBTD 1-23-02 ND WH; PULL 5-1/2" (1-27-02 RU HALLIBURTON; SPLUG FROM 8125 TO 8825'. SWO ROTARY TOOLS.  Name (Printed/Typed) BEV-HATF	true and correct.	give subsurface locations and measure the Bond No. on file with BLM/BI tults in a multiple completion or read only after all requirements, included a subsurface of the subsur	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir sosquent reports shall be sew interval, a Form 316 a, have been completed,  P 35' OF CMT ON  PG; YIELD OF .94) EUNICE WS; WEL  CEPTED FOR  GARY GOUP PETROLEUM EN	ent markers and zones. filed within 30 days of 30-4 shall be filed once and the operator has CMT L SD,	
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final Abdetermined that the site is ready for full the worfollowing completed. Final Abdetermined that the site is ready for full the worfold that the site is ready for full that the sit	true and correct.	give subsurface locations and measure the Bond No. on file with BLM/BI sults in a multiple completion or read only after all requirements, included only after all requirements, included the Bond No. on File Wilson and State 12150'; TST TO 1000 IH W/2-7/8" TBG TO 8825'; SS H (0.2% HR5 & 0.3% CF 5 HRS; ND BOP & CAP WE 5 HRS; ND BOP & CAP WE 5 Title Date 01/28/2	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir soscquent reports shall be see winterval, a Form 316 a, have been completed,  P 35' OF CMT ON  PG; YIELD OF .94)  EEDTED FOR  GARY GOUF  PTROLEUM ZO	ent markers and zones. filed within 30 days of 30-4 shall be filed once and the operator has CMT_L SD,	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit WO TO SET CIBP OVER 3RD 1-22-02 MI RU EUNICE WS; FCIBP @ 12,150' FOR A PBTD 1-23-02 ND WH; PULL 5-1/2" (1-27-02 RU HALLIBURTON; SPLUG FROM 8125 TO 8825'. WO ROTARY TOOLS.	true and correct.  Approval of this notice does neathly title to those rights in the special special and correct.	give subsurface locations and measure the Bond No. on file with BLM/BI sults in a multiple completion or read only after all requirements, included only 2 CSG;  BP @ 12150'; TST TO 1000  IH W/2-7/8" TBG TO 8825'; SS H (0.2% HR5 & 0.3% CF SHRS; ND BOP & CAP WE  Title  Date 01/28/2  R FEDERAL OR STATE	# - OK; DUM FR3 @17.4 P LL; RD & MC	rtical depths of all pertir sosquent reports shall be sew interval, a Form 316 a, have been completed,  P 35' OF CMT ON  PG; YIELD OF .94) EUNICE WS; WEL  CEPTED FOR  GARY GOUP PETROLEUM EN	ent markers and zones. filed within 30 days of 30-4 shall be filed once and the operator has CMT_L SD,	

KZ

BOZMETT OLLICE

BOBEVO CHENCE

2002 JAN 30 AM 8:36

BECEINED