

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. 20059	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Highland Production Company	8. Farm or Lease Name J.A. Koontz
3. Address of Operator P.O. Box 1406, Odessa, Texas 79767-6326	9. Well No. #2
4. Location of Well UNIT LETTER <u>H</u> <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>1650</u> FEET FROM THE <u>North</u> LINE, SECTION <u>14</u> TOWNSHIP <u>25</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat Jalmat
15. Elevation (Show whether DF, RT, GR, etc.) 3142.8 G.L.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-30-83 Set 8 5/8" Csg. in 12 1/4" hole @ 1083' cement w/585 sx, circulated.  
Wait 4 hrs. - test 1000 lbs. - 15 minutes.

11-04-83 Set 5 1/2" csg. in 7 7/8" hole @ 3285' cement w/710 sx - wait 24 hrs. - test  
1000 lbs. - 15 minutes.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

HIGHLAND PRODUCTION COMPANY

SIGNED Marvin L. Smith

TITLE President

DATE 1/18/84

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE JAN 30 1984

CONDITIONS OF APPROVAL, IF ANY:

APR 30 1984  
O.C.D.  
TREAS OFFICE