


ASE ROTARY TABLE

Flow line will have to be made
to fit UNDER Rotary.

Optional



RECEIVED
NOV 27 1985
O.C.D.
HOBBS OFFICE