


ASE ROTARY TABLE

Flow line will have to be made
to fit UNDER Rotary.

Optional



RECEIVED
DEC 2 - 1985
O.C.D.
HOBBS OFFICE