## Submit 3 Copies to Appropriate District Office

DISTRIC	TI		
P.O. Box	1980, Hobbi	, NM	88240

## En

ubmit 3 Copies o Appropriate	Santa Fe, New Mexico 87504-2088		Form C-103 Revised 1-1-89  WELL API NO. 30-025-30196  5. Indicate Type of Lease STATE XX FEE		
District Office DISTRICTI O. Box 1980, Hobbs, NM 88240					
OISTRICT II O. Drawer DD, Artesia, NM 88210					
DISTRICT III 0000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. B-9519		
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name West Dollarhide Queen Sand Unit		
. Type of Well: OIL GAS	one Water I	njection	Offic		
WELL WELL WELL Name of Operator			8. Well No. 108		
Sirgo Operating, I	inc.		9. Pool name or Wildcat		
P.O. Box 3531, Mic	iland, Texas 79702		Dollarhide Queen		
Well Location		Line and 380	Feet From The West Line		
NOTICE OF IN ERFORM REMEDIAL WORK  EMPORARILY ABANDON  ULL OR ALTER CASING	10. Elevation (Show whether II 3178 GR Appropriate Box to Indicate NTENTION TO: PLUG AND ABANDON CHANGE PLANS	Nature of Notice, R SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Star	SSEQUENT REPORT OF:  ALTERING CASING  G OPNS. PLUG AND ABANDONMENT  EMENT JOB  t injection		
<ol> <li>Describe Proposed or Completed Opwork) SEE RULE 1103.</li> </ol>	erations (Clearly state all pertinent details, an	d give pertinent dates, incl	uding estimated date of starting any proposed		
Set pkr @ drum WT-12	'8" x 5-1/2" AD-1 injecti 3608', SN @ 3605' & tbg 270 pkr fluid. Test backs ad & tie into injection l	ide to 500# fo	TOO DDIS 2% ROD WYORE		
2-23-90 Tie into h	neader & start injection.	Inject w/500	BWPD @ 950# psi.		
I hereby certify that the information above is					

CONDITIONS OF APP	ROVAL, IF ANY:			
APTROVED BY	DISCORTOR POWERVISOR	ти	DATE	WAIL TO 1990
(This space for State				MAR 1 6 1990
TYPE OR PRINT NAM	Bonnie Atwater		TELET	NONE NO. 915/685-0878
SIGNATURE	ATTION CILCUMENT	· IIICE		
hereby certify that I	the information above is true and complete to the best of my knowledg	mne Production Technician	DATE	3-14-90
		and halis		
2-23-90	The Theo header a state of			
2-23-90	Tie into header & start injecti	on. Inject w/500 BWPD @ 950#	psi.	
	NU wellhead & tie into injection	n line.		