

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 30228
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-9613
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	92
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>F</u> : <u>1585</u> Feet From The <u>NORTH</u> Line and <u>1460</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ Acidize & Scale Squeeze

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-15-99: MIRU. UNSEAT PUMP & POH W/RDS & PMP. BLED OFF CSG & NDWH & INSTL BOP. UNSET TAC. TIH W/BIT & BAILER ON 2 7/8" TBG TO 6474'. BAILED DN TO 6484' & COULD GO NO FURTHER.
3-16-99: BLED DN WELL. TIH W/SONIC HAMMER TOOL & ACIDIZE PERFS W/3500 GALS 15% NEFE. DROP BALL & MADE 2 SWAB RUNS. HOLE IN FLOWLINE.
3-17-99: BLED DN WELL. TIH W/MUD JOINT, SN, 2 7/8" TBG, TAC. TAC SET @ 6283'. SN @ 6413'. NDBOP. FLANGE UP WH. TIH W/PUMP & GAS ANCHOR, SNKR BARS, & RDS. HANG ON & LOAD & TEST. SPACE OUT. RIG DOWN.
3-21-99: ON 24 HR OPT. PUMPING 47 BO, 77 BW, & 41 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 3/26/99
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY CRIMINAL JUSTICE TITLE CRIMINAL JUSTICE DATE 3/26/99
CONDITIONS OF APPROVAL, IF ANY: