

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 87240

District II
811 South First, Artesia, NM 87210

District III
1000 Rio Brazos Rd., Aztec, NM 87410

District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-30295
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other WIW <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator SAGA PETROLEUM LLC		6. State Oil & Gas Lease No. B-9613
3. Address of Operator 415 W Wall, Suite 1900 Midland, TX 79701		7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN UNIT Agreement 8910084910
4. Well Location Unit Letter <u>F</u> : <u>2100</u> feet from the <u>NORTH</u> line and <u>1630</u> feet from the <u>WEST</u> line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM County <u>LEA</u>		8. Well No. <u>135</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3167		9. Pool name or Wildcat Dollarhide Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: Sqz btm perms ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOBS ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

TD 3950' PBTD 3894' Perfs 3633'-3800' 5-1/2" AD-1 pkr @ 3491'
12-1/4" hole - 8-5/8" 24# csg @ 414', cmt'd w/250 sx, TOC @ surface by circ
7-7/8" hole - 5-1/2" 15.5# csg @ 3950', cmt'd w/1000 sx, TOC @ surface by circ

Intend to sqz lwr perms 3736' - 3800' w/20 sx cmt leaving top perf @ 3633' & btm @ 3714'
Leave pkr @ 3491'
Return well to injection

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE PROD ANALYST DATE 08/13/2001

Type or print name BONNIE HUSBAND Telephone No. (915)684-4293

(This space for State use)

APPROVED BY _____ TITLE _____ ORIGINAL SIGNED BY _____ DATE _____

Conditions of approval, if any: