

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30 025 30826

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

B-9613

7. Lease Name or Unit Agreement Name

WEST DOLLARHIDE DRINKARD UNIT

8. Well No.

104

9. Pool Name or Wildcat

DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator  
205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter J : 2541 Feet From The SOUTH Line and 1380 Feet From The EAST Line

Section 32 Township 24S Range 38E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

DRILL OUT CIBP ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-21-00: MIRU. UNSEAT PUMP. NDWH. NUBOP. TIH W/BIT, DC'S, & TBG TO 2110'.

6-22-00: TIH TO 6644'. BREAK CIRC W/150 BFW. DRILL SAND. CMT TO 6658'. DRILL ON CIBP 6658-6660. PLUG TURN LOOSE. CHASE TO 6675'. DRILL ON PLUG & PUSH TO 6677'. CIRC CLN & PULL BIT TO 6426'.

6-23-00: LOWER BIT 642'-6677'. DRILLING ON JUNK, SCALE. DRILL TO 6727'. PULL BIT TO 5445'.

6-26-00: TIH W/CONE BLSTER MILL, DC'S ON TBG. TAG 6727'. BREAK CIRC. MILL ON JUNK & CIBP @ 6660'. PUSH TO 6920'.

6-27-00: TIH W/PURGE VALVE, SN, TBG, TAC. TBG @ 6793'. SN @ 6759'. TAC @ 6369'. NDBOP. NUWH. DUMP 5 GALS 3036 DN TBG. TIH W/SLOTTED GAS ANCHOR, PUMP, SNKR BARS, RDS. HUNG ON LOAD & TEST. RIG DOWN. PUMPING @ 4:30 PM

7-14-00: ON 24 HR OPT. PUMPED 14 BO, 95 BW, & 18 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 8/23/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

ORIGINAL SIGNED BY CHRIS WILLIAMS

CONDITIONS OF APPROVAL, IF ANY:

TITLE Deputy Director

DATE 8/23/00

DeSoto/Nichols 1-1-89