State of New Mexico

Submit 3 Copies to Appropriate District Office	Energy, Minerals and Natural		Form C-103 Revised 1-1-89
DISTRICT I P.O. Bon. 1980, Hobbe, NM 88240	OIL CONSERVAT	2088	WELL API NO. 30-025-30826
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	co 87504-2088	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			STATE X FEE 6. State Oil & Gas Lesse No. B-9613
SUNDRY NOT	ICES AND REPORTS ON W	VELLS	
	RVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A PERMIT"	7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
OF X OVER COAS	OTHER		
Name of Operator TEXACO PRODUCING INC.			2. Well No.
3. Address of Operator			104
	dland, Texas 79702		9. Pool name or Wildcat
4. Well Location			DOLLARHIDE TUBB DRINKARD
Unit Letter _J :25	Township 24-SOUTH	Line andRange 38-EAST	1380 Feet From The EAST Line NMPM LEA County
	10. Elevation (Show wheth GR-3184', KB-320	her DF, RKB, RT, GR, etc.) 02°	
11. Check	Appropriate Box to Indicat	te Nature of Notice, F	Report, or Other Data
NOTICE OF IN	TENTION TO:		SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB X
OTHER:	[OTHER: SPUD & SI	JRFACE CASING
work) SEE RULE 1103. 1. EXETER RIG #65 SPUD 14 3 2. RAN 28 JTS OF 11 3/4, 42	3/4 HOLE @ 10:00pm 01-31 2#, J-55, ST&C CASING SET / 1000 SACKS CLASS H w/ T TO 500#. FOR 30 MINUTES FROM 12:0	I-91. DRILLED TO 120 @ 1200'. RAN 10 CEN 2% Cacl2 @ 15.6ppg.	PLUG DOWN @ 9:45am 02-02-91.

-6884620