

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Pronghorn Management Corporation

3. Address and Telephone No.

P.O. Box 1772 Hobbs, N.M. 88240 505-393-8386

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

"G" 1975' FNL + 1980' FEL
S4-T255-R33E

5. Lease Designation and Serial No.

NM 19859

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Gila 4 Deep #1

9. API Well No.

30-025-30872

10. Field and Pool, or Exploratory Area

Vaca Draw Atoka

11. County or Parish, State

Lea

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIAU well service unit. Install B.D.P. + test.
2. Release from permanent packer. P.O.H.
3. Set C.I.B.P. @ $\pm 14,000'$, Cap w/ 35' cement.
4. Trip in hole w/ packer. Set @ $\pm 12,900'$.
5. Perforate Wolfcamp formation 13,165-13,940'.
6. Acidize if necessary.
7. Bring well in + clean up.
8. Return well to production.
9. Rig down. move out rig

Estimated date to start:
6/3/99

14. I hereby certify that the foregoing is true and correct

Signed G.A. Baber Title Intervenor

Date 6/3/99

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

Title PETROLEUM ENGINEER

Date JUN 03 1999

Approved by _____
Conditions of approval, if any: