

STRICT I

J. Box 1980, Hobbs, NM 88240

STRICT II

J. Box Drawer DD, Artesia, NM 88210

STRICT III

100 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002530876
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	LC-067968
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	99
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator TEXACO EXPLORATION & PRODUCTION INC.

Address of Operator 205 E. Bender, HOBBS, NM 88240

1. Well Location

Unit Letter O : 1108 Feet From The SOUTH Line and 1394 Feet From The EAST Line

Section 30 Township 24S Range 38E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ PB ABO, ACID FRAC DRINKARD

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-30-98: MIRU. UNSEAT PUMP. PULL UP 42' STUCK PUMP. BACK OFF RODS. TOH W/ROD, LINER. NDWH. NUBOP. UNSET ANCHOR. WRK TBG FREE. TOH W/TBG DRAGGING. TOH W/TBG, SN, & OPSMA. TBG SET @ 6824'.
7-01-98: TIH W/BIT & CSG SCRAPER ON 2 7/8" TBG TO 6780'. WELLCHECK TBG OUT OF HLE. SET CIBP @ 6670'. COLLAR @ 6673'. TIH W/BAILER & DUMP 15' CMT ON TOP OF PLUG. NEW PBTD 6655'. TIGHT SPOT @ 5964'. TIH W/MIL COR FRAC PKR. PSA 6382'-59' ABOVE TOP PERF.
7-02-98: LOAD & TEST BACKSIDE TO 500#-OKI. ACIDIZE DRINKARD PERFS 6451-6582' W/1200 GALS 15% NEFE. SURGE OFF BALLS & ACID FRAC SAME DRINKARD PERFS W/1000 GALS 15% DGA FOLLOWED BY 3000 GALS 15% NEFE. FLSH W/42 BBLS PROD WTR. FLOW TRO FRAC TANK TO 0#. FL @ SURF. END FL @ 2400'. SCALE SQUEEZED DRINKARD PERFS 6451-6582' W/2 DRUMS TECHNI-HIB 793. FLWH W/250 BBLS PROD WTR.
7-06-98: REL PKR. RAN MA, SN, 2 7/8" TBG. REM BOP. LAND BTM OF MA @ 6623'. SN @ 6591'. RAN GAS ANCHOR ON PUMP, SNKR BARS & RODS.
7-07-98: TIH W/RDS. LONGSTROKED PUMP & PUMPED UP WELL-NO ELECTRICITY. FL @ 250' FR SURF. RIG DOWN.
7-08-98/7-20-98: PUMPING AND TESTING.
7-20-98: ON 24 HR OPT. PUMPED 32 BO, 98 BW, & 17 MCF. GOR-531. GRAV-38.7 @ 60.
PERFS 6451-6582' DRINKARD
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 8/3/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY ORIN TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: