

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-31482

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-9613

7. Lease Name or Unit Agreement Name
WEST DOLLARHIDE DRINKARD UNIT

8. Well No.
113

9. Pool name or Wildcat
DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION AND PRODUCTION INC.

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

4. Well Location
Unit Letter M : 136 Feet From The SOUTH Line and 1246 Feet From The WEST Line
Section 32 Township 24-SOUTH Range 38-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR-3140', KB-3158'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU COMPLETION UNIT. TIH & TAG PBTD @ 7385'. TESTED CASING TO 3000# FOR 30 MINUTES. 10-7-92.
2. UNION RAN GR-CCL FROM 7385' TO 6200'. PERF w/ 1 JSPF: 7166-72, 7178-86, 7194-97, 7209-16. 26 HOLES.
3. TIH & SET RBP @ 7095' & TESTED TO 3000#. PERFORMED w/ 1 JSPF: 6788-98, 6818-22, 6841-45, 6860-66, 6894-98, 6950-55, 6958-60, 6972-80, 6992-96, 7034-38. 59 HOLES. DOWELL ACIDIZED w/ 5300 GAL 15% NEFE. 10-13-92. SWB 64 BO & 90 BLW IN 4 HOURS.
4. MOVED RBP TO 6730' & TESTED TO 3000#. PERFED w/ 2 JSPF: 6308-12, 6331-34, 6338-51, 6356-66, 6370-72, 6378-6400, 6506-09, 6538-42, 6549-55, 6558-71, 6610-15, 6622-28, 6644-47, 6654-58. 196 HOLES. DOWELL ACIDIZED w/ 10300 GAL 15% NEFE 10-16-92. FLOWED 8 BO & 196 BLW IN 6 HOURS.
5. TOH WITH RBP.
6. TIH WITH 2 7/8 TUBING, PUMP AND RODS.
7. PUMPED 43 BO AND 313 BLW IN 15 1/2 HOURS 10-20-92.
8. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham / cwH TITLE DRILLING OPERATIONS MANAGER DATE 10-21-92
TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

OCT 26 '92