

ISTRICT I
.O. Box 1980, Hobbs, NM 88240

ISTRICT II
.O. Box Drawer DD, Artesia, NM 88210

ISTRICT III
000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-31488

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil / Gas Lease No.
B-9613

7. Lease Name or Unit Agreement Name
WEST DOLLARHIDE DRINKARD UNIT

8. Well No.
121

9. Pool Name or Wildcat
DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER INJECTION

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter E : 2176 Feet From The NORTH Line and 656 Feet From The WEST Line
Section 32 Township 24S Range 38E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.) GR-3150', KB-3163'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Perf, Acidize, Clean out ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-26-99: MIRU. FLOW WELL TO FRAC TANK.
5-27-99: NDWH. NUBOP. REL PKR & LOWER TO 6454'. TAG 10' BELOW PKR. C/O RAMS. RU REV UNIT. TIH W/USED BIT. STOP BIT @ 6411'.
5-28-99: TIH W/TBG. TAG @ 6452'. BREAK CIRC & C/O SCALE 6452-6820'. RIG DOWN REV UNIT.
5-29-99: TIH W/CSG G JN. PERF DRINKARD FORMATION 6441-44, 6448-54, 6456-61. TIH W/PKR, & SN ON TBG. PSA 6392'. PRESS CSG TO 500#-OK. ACIDIZE DRINKARD PERFS 6441-6574' W/6500 GALS 15% NEFE HCL & 3000# RK SLT. PUMP IN 4 STGS OF ACID. FLOW WELL.
6-01-99: REL PKR. KILL W/40 BBLS BRINE. CHANGE RAMS IN BOP. TIH W/PUMP OUT PLUG & PKR. TEST TO 2000 PSI. LEFT WELL FLOWING.
6-02-99: SET PKR @ 13'. KB @ 6379'. REL ON/OFF TOOL. RU PUMP TRUCK. CIRC W/PKR FLUID. LATCH ON/OFF TOOL. NDBOP. NUWH. PSI CSG & PKR TO 500 PSI. CHART FOR 30 MIN FOR NMOC. RIG DOWN PUMP TRUCK. INSTL WELL HEAD.
6-17-99: ON 24 HR INJ. INJ'D 171 BWPD @ 1500 PSI.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/22/99

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

ORIGINAL SIGNED BY
GARY WINK
FIELD REPRESENTATIVE II

APPROVED BY _____ TITLE _____ DATE 6-28-99

CONDITIONS OF APPROVAL, IF ANY:

JCS

DeSoto/Nichols 12-93 ver 1.0

SCR 01/9
B 8/13/01
05

